

Report ID: 19,118,382 Version: 1 11 Mar 2019 Created:

| Make: | KIA | Model: | Sorento | Body Style: | SUV | | Pass | Fail | N/A |
|--|---------------------------|-----------------|------------------------|--------------------|----------------------|--------------------------------------|----------|--------|-----|
| Year: | 2004 | Registration: | CED245 | Reg Expiry: | 31 May 2019 | Engine | I | L | I |
| WoF Expiry: | | Odometer: | 228,952 Kms | Good No: | 19118382 | Oil level | ~ | | |
| VIN: | KNAJC523845210576 | Next Service: | 227000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | | 6 | Danta harra nat | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | nical inspection prior to | purchase and tl | his can be arranged fo | or an additional o | harge. | Coolant condition | ~ | | |
| | | _ | | | | Performance | V | | |
| Key: | | -0 | LS | -161- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | | | | | | Operation | ~ | | |
| R = rust PT = paint defe | | | | \int | JHIH | Noise | ~ | | |
| C = crack | | | | | | Clutch | • | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | |
| * = decals | PSC 916 | | | - NL | ELLER T | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S PT S PT | | | | | | Performance | ~ | | |
| | | Note: son | ne defects & blemishes | may not be disr | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Tyres (lowest observed tread | | oftvre | 25) |
| Remote poor | | | | | | Left front 6 mm | | | |
| | | | | | | Right front | | 5 | mm |
| | | | | | | Left rear | | 6 | mm |
| Conditions Duving Rody Inspections | | | | | | Right rear | - | - | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear 8 m Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Lifter rattle | - | | | | | Suspension performance | ~ | | |
| Dirty | | | | | | Steering performance | ~ | | |
| Oil leak | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | V | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats Average | | | | | | Head lights | ~ | | |
| Seals | | | | | | | | | |
| Carpets | Average | | | | | Tail lights Indicators | ~ ~ | | |
| D 1 | Average | | | | | Dashboard warning lights | | | |
| Panels | | | | | | Wipers (front & rear) | v | | |
| Dashboa | ard Average | | | | | Window winder FL | ~ ~ | | |
| | | | | | | Window winder FL Window winder FR | | | |
| General Comments | | | | | | Window winder FR Window winder RL | v | | |
| | | | | | | | v | | |
| | | | | | | Window winder RR | v | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Engine Ti | ming Mechanism: | Cambel | t | | | Remote locking | | ~ | |
| Evidence of Cam Belt Replacement: Yes Kms: 112,000 | | | | | | Sat. Nav. (basic test only) | | | ~ |
| | | | | 1115. [] | 2,000 | Reversing camera | | | ~ |
| Inspecte | d by: Stuart Melbourr | ne | | | | Date: 11 Mar 20 | 19 | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: