

Report ID: 19,118,812 Version: 1 08 Apr 2019 Created:

Make:	Hyundai	Model:	Tucson	Body Style:	Wagon		Pass	Fail	N/A
Year:	2005	Registration:	DDK461	Reg Expiry:	17 May 2019	Engine			L
WoF Expiry:	11 Jun 2019	Odometer:	298,069 Kms	Good No:	19118812	Oil level	~		
VIN:	KMHJN81DR5U08815	Next Service:		Service Histor		Smoke & fumes	~		
					,	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S D W	-0	S D SC S D SC		D SC	Radiator / Hoses (visual)	~		
S = scratch D = dent S C W						Transmission			
						Operation V			
R = rust				10		Noise	-		
PT = paint def C = crack	ect			+	S D	Clutch	~		
P = pin dent	Ho	KI							~
* = decals	sc pp				ELLAR SW	CV joints	レ レ		
SC = stone chips						Wheel bearings			
W = significant scuffs W S C W S SC W D SC						Brakes			1
						Performance	~		<b></b>
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
						Left front	4.	6	mm
						Right front	5.	2	mm
						Left rear	6	<b>i</b>	mm
Conditions During Body Inspection: Dry						Right rear	5.9 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underbo	ody inspection					Suspension performance	~		
						Steering performance	~		
Shoo							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	both back	and drivers doo	r panels have holes			Dashboard warning lights	~		
	. Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 226,112									~
L									
Inspected by: Melissa Haggerty Date: 08 Apr 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....