

Report ID: 19,118,968 Version: 1 13 Mar 2019 Created:

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:		Reg Expiry:	18 Oct 2019	Engine			
WoF Expiry:		Odometer:	112,868 Kms	Good No:	19118968	Oil level	~		
VIN:	KMHBT51DR6U45706		112,000 Kills	Service Histor		Smoke & fumes	~		
	1				. 110	Performance	~		
	port is not a warranty					Noise	•	~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	SPT	-0	SPTP SP		S P	Radiator / Hoses (visual)	V		~
S = scratch						Transmission			V
D = dent	s sc all			1 - L	BIDS	Operation	~		
R = rust				10	7HIX —	Noise	~		
PT = paint defe C = crack	ect M			+	SC	Clutch	V		
P = pin dent	Ho				JIII —				~
* = decals	s sc pp			AL-	EL SPT	CV joints	~		
SC = stone chips						Wheel bearings			~
W = significant scuffs W S S S W S						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Audio antenna missing						Tyres (lowest observed tread depth of tyres)			
Wiper surface rust Rear bumper misaligned						Left front	3.	.5	mm
Tail gate interior panel missing						Right front	3.	.5	mm
Stone chips on front windscreen						Left rear	3	3	mm
Conditions During Body Inspection: Wet						Right rear 3 mn			mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Not hoisted	l					Suspension performance	~		
						Steering performance	~		
						Shock absorbers			~
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		1
Dashboa	rd					Window winder FL	~		
	•					Window winder FR	~		
General Comments					Window winder RL	~			
Engine vibration						Window winder RR	~		
Engine noisy AC compressor noisy					Rear view mirrors	~			
Driver door cards falls						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Wet Centr							~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
Inspected by: Xinghui Lin Date: 13 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: