

## **Basic Vehicle Condition Guide**

Report ID: 19,119,149


Version:

Created: 14 Mar 2019

Make: Model: Volkswagen Amarok **Body Style:** Utility Year: 2011 Registration: GDQ894 Reg Expiry: 19 Sep 2019 WoF Expiry: **Odometer: Good No:** 28 Mar 2020 79,530 Kms 19119149 VIN: WV1ZZZ2HZB8055357 **Next Service:** 88000 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

| <u>Interior Comments</u> |      |  |  |  |  |
|--------------------------|------|--|--|--|--|
| Seats                    | Good |  |  |  |  |
| Carpets                  | Good |  |  |  |  |
| Panels                   | Good |  |  |  |  |
| Dashboard                | Good |  |  |  |  |

**General Comments** 

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Dion Mair

Evidence of Cam Belt Replacement: No

Kms:

|                              | Pass                                    | Fail    | N/A |
|------------------------------|-----------------------------------------|---------|-----|
| Engine                       |                                         |         |     |
| Oil level                    | ~                                       |         |     |
| Smoke & fumes                | <ul><li>V</li><li>V</li><li>V</li></ul> |         |     |
| Performance                  | ~                                       |         |     |
| Noise                        | ~                                       |         |     |
| Cooling System               |                                         | •       |     |
| Coolant condition            | ~                                       |         |     |
| Performance                  | \( \triangle \)                         |         |     |
| Radiator / Hoses (visual)    | ~                                       |         |     |
| Transmission                 |                                         |         |     |
| Operation                    | ~                                       |         |     |
| Noise                        | ~                                       |         |     |
| Clutch                       | ~                                       |         |     |
| CV joints                    | \( \times \)                            |         |     |
| Wheel bearings               | ~                                       |         |     |
| Brakes                       |                                         | •       | •   |
| Performance                  | ~                                       |         |     |
| Hand Brake                   | ~                                       |         |     |
| Tyres (lowest observed tread | depth                                   | of tyre | es) |
| Left front                   | 10                                      | 0.0     | mm  |
| Right front                  | 10.0                                    |         | mm  |
| Left rear                    | 10.0                                    |         | mm  |
| Right rear                   | 10.0                                    |         | mm  |
| Spare                        |                                         | Yes     |     |
| Suspension                   |                                         |         |     |
| Suspension performance       | ~                                       |         |     |
| Steering performance         | <i>V</i>                                |         |     |
| Shock absorbers              | >                                       |         |     |
| Air Conditioning / Heater    |                                         |         |     |
| Operation                    | ~                                       |         |     |
| Electrical / Accessories     |                                         |         |     |
| Head lights                  | ~                                       |         |     |
| Tail lights                  | ~                                       |         |     |
| Indicators                   | ~                                       |         |     |
| Dashboard warning lights     | \( \times \)                            |         |     |
| Wipers (front & rear)        | <b>'</b>                                |         |     |
| Window winder FL             | <b>'</b>                                |         |     |
| Window winder FR             | ~                                       |         |     |
| Window winder RL             | \( \times \)                            |         |     |
| Window winder RR             | ~                                       |         |     |
| Rear view mirrors            | ~                                       |         |     |
| Radio (basic test only)      | ~                                       |         |     |
| CD (basic test only)         | ~                                       |         |     |
| Number of keys               | 2                                       |         |     |
| Central locking              | ~                                       |         |     |
| Remote locking               | ~                                       |         |     |
| Sat. Nav. (basic test only)  |                                         |         | V   |

I have read and understood this condition guide.

| Name <sup>.</sup> |  |  |  |
|-------------------|--|--|--|
|                   |  |  |  |

12 Mar 2019

1

Reversing camera