


|                    |                  |                      |            |                         |             |
|--------------------|------------------|----------------------|------------|-------------------------|-------------|
| <b>Make:</b>       | Mitsubishi       | <b>Model:</b>        | Mirage     | <b>Body Style:</b>      | Hatchback   |
| <b>Year:</b>       | 2016             | <b>Registration:</b> | JSQ561     | <b>Reg Expiry:</b>      | 14 Apr 2019 |
| <b>WoF Expiry:</b> | 29 Mar 2020      | <b>Odometer:</b>     | 24,464 Kms | <b>Good No:</b>         | 19119901    |
| <b>VIN:</b>        | MMAXTA03AFH00569 | <b>Next Service:</b> | nil        | <b>Service History:</b> | No          |

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs


**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**
**Interior Comments**

|           |      |
|-----------|------|
| Seats     | Good |
| Carpets   | Good |
| Panels    | Good |
| Dashboard | Good |

**General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

|                                                     | Pass | Fail | N/A |
|-----------------------------------------------------|------|------|-----|
| <b>Engine</b>                                       |      |      |     |
| Oil level                                           | ✓    |      |     |
| Smoke & fumes                                       | ✓    |      |     |
| Performance                                         | ✓    |      |     |
| Noise                                               | ✓    |      |     |
| <b>Cooling System</b>                               |      |      |     |
| Coolant condition                                   | ✓    |      |     |
| Performance                                         | ✓    |      |     |
| Radiator / Hoses (visual)                           | ✓    |      |     |
| <b>Transmission</b>                                 |      |      |     |
| Operation                                           | ✓    |      |     |
| Noise                                               | ✓    |      |     |
| Clutch                                              |      |      | ✓   |
| CV joints                                           | ✓    |      |     |
| Wheel bearings                                      | ✓    |      |     |
| <b>Brakes</b>                                       |      |      |     |
| Performance                                         | ✓    |      |     |
| Hand Brake                                          | ✓    |      |     |
| <b>Tyres</b> (lowest observed tread depth of tyres) |      |      |     |
| Left front                                          | 2.5  | mm   |     |
| Right front                                         | 2.5  | mm   |     |
| Left rear                                           | 3    | mm   |     |
| Right rear                                          | 3    | mm   |     |
| Spare                                               | Yes  |      |     |
| <b>Suspension</b>                                   |      |      |     |
| Suspension performance                              | ✓    |      |     |
| Steering performance                                | ✓    |      |     |
| Shock absorbers                                     | ✓    |      |     |
| <b>Air Conditioning / Heater</b>                    |      |      |     |
| Operation                                           | ✓    |      |     |
| <b>Electrical / Accessories</b>                     |      |      |     |
| Head lights                                         | ✓    |      |     |
| Tail lights                                         | ✓    |      |     |
| Indicators                                          | ✓    |      |     |
| Dashboard warning lights                            | ✓    |      |     |
| Wipers (front & rear)                               | ✓    |      |     |
| Window winder FL                                    | ✓    |      |     |
| Window winder FR                                    | ✓    |      |     |
| Window winder RL                                    | ✓    |      |     |
| Window winder RR                                    | ✓    |      |     |
| Rear view mirrors                                   | ✓    |      |     |
| Radio (basic test only)                             | ✓    |      |     |
| CD (basic test only)                                | ✓    |      |     |
| Number of keys                                      | 2    |      |     |
| Central locking                                     | ✓    |      |     |
| Remote locking                                      | ✓    |      |     |
| Sat. Nav. (basic test only)                         |      |      | ✓   |
| Reversing camera                                    |      |      | ✓   |

Inspected by: Sudhin Ramachandran

Date: 15 Mar 2019

I have read and understood this condition guide.

Name: .....

Signature: .....