

## **Basic Vehicle Condition Guide**

Report ID: 19,120,043


Version: 1

Created: 13 Mar 2019

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2009 Registration: FBA864 Reg Expiry: 19 Jul 2019 WoF Expiry: **Odometer: Good No:** 217,348 Kms 19120043 VIN: KMHSH81WR9U50371 **Next Service:** 230000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Paint defect and decal mark around body

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Not hoisted

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	screw holes on dash		
Dashboard	crack on odometer unit		

## **General Comments**

Tow bar missing

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** Yes Kms: 151,968

	Pass	Fail	N/A
Engine	•	•	•
Oil level	~		
Smoke & fumes	\( \triangle \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)			~
Transmission	Į.		
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings			~
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l d depth	of tyre	 es)
Left front	I	 3	mm
Right front	-	7	mm
Left rear	6		mm
Right rear	5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers			~
Air Conditioning / Heater	ı		
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\( \times \) \( \t		
Window winder FL	~		
Window winder FR	V		
Window winder RL	~		
Window winder RR			
Rear view mirrors	<b>V</b>		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	ı	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			1

Signature: .....

13 Mar 2019 Inspected by: **Bobby Zhong** 

Name: .....