

I have read and understood this condition guide.

Report ID: 19,120,062 Version: 1 12 Mar 2019 Created:

Signature:

Make:	Toyota	Model:	Corolla	Body Style:	Wagon		Pass	Fail	N/A
Year:	2013	Registration:	GTS594	Reg Expiry:	22 Jul 2019	Engine			
WoF Expiry:	06 Jul 2019	Odometer:	130,789 Kms	Good No:	19120062	Oil level	~		
VIN:	JTDZT4GEX0L000920	Next Service:	126555	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and the	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SP SP	-161-	Р	Radiator / Hoses (visual)	•		~
S = scratch						Transmission			
D = dent	sc 6/6				EII SD	Operation	~		
R = rust PT = paint def				\prod	JHIA	Noise	~		
C = crack						Clutch	•		~
P = pin dent						CV joints	~		
* = decals	sc pip			AL.	EIIR	Wheel bearings	•		~
SC = stone chips						Brakes			~
W = significant scuffs W S S									
						Performance	~		
Body Ins	pection Comments	Note: som	ne defects & blemishes	s may not be disp	hayed in the diagram	Hand Brake		<i>C</i> .	Ļ
					Tyres (lowest observed tread depth of tyres)				
						Left front	4 mm		-
						Right front	4 mm		-
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Not hoisted	1					Suspension performance	~		
						Steering performance	~		
						Shock absorbers			~
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Comoto	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Bobby Zhong Date: 12 Mar 2019									

Name: