

Basic Vehicle Condition Guide

Report ID: 19,121,295


Version:

Created: 13 Mar 2019

Make: Model: Holden Barina **Body Style:** Hatchback Year: 2006 Registration: DNS979 Reg Expiry: 03 May 2019 **Odometer:** WoF Expiry: 27 Mar 2019 122,134 Kms **Good No:** 19121295 VIN: KL3SF086E7B716998 Next Service: 128119 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

RF door mirror casing scratched ,bonnet faded,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak,

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	VVV		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission	•		
Operation	~		
Noise	~		
Clutch	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4		mm
Right front	5		mm
Left rear	5		mm
Right rear	5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation		~	
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \) \(\t		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

I have read and understood this condition guide.

Donovan Matara

Name:

Signature:

13 Mar 2019

Reversing camera