

Report ID: 19,121,305 Version: 1 14 Mar 2019 Created:

Make:	Hyundai	Model:	Getz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:	CLM202	Reg Expiry:	11 Jul 2019	Engine	1	i	1
WoF Expiry:	14 Jan 2020	Odometer:	71,064 Kms	Good No:	19121305	Oil level	V		
VIN:	KMHBT51HR5U32052	Next Service:	80,000	Service Histor	y: No	Smoke & fumes	~		
						Performance	V		
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismontled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SP	-0	S PT S	-01-	s	Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	s dia			715	HILV	Operation	V		
PT = paint defe	ect NP	F		$\left(\left \right\rangle \right)$		Noise	r		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	DSC 916			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S FT S PT S PT S PT						Performance	~		
Dedular		Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
RH tail lamp cracked						Left front 7 mm			
						Right front		7	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear		7	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~	-	
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	V		
						Radio (basic test only)	~		
						CD (basic test only)	V		
						Number of keys	1	1	L
Road Conditions During Test Drive: Dry						Central locking	~		
, ,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
							1		
Inspecte	d by: Mathew Varghe	se				Date: 14 Mar 20	19		

I have read and understood this condition guide.

Name:

Signature: