

## **Basic Vehicle Condition Guide**

Report ID: 19,121,852


Version:

Created: 19 Mar 2019

Make: Model: Mitsubishi Mirage **Body Style:** Hatchback Year: 1996 Registration: UQ5529 Reg Expiry: 01 Apr 2019 WoF Expiry: **Odometer:** 18 Sep 2019 274,590 Kms **Good No:** 19121852 VIN: 7A1MM1L24TP033417 Next Service: 279,000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Right rear window seal poor Front windscreen small stone chips

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Engine oil leak

Interior Comments			
Seats	Good		
Carpets	Average		
Panels	Good		
Dashboard	Good		

## **General Comments**

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt **Evidence of Cam Belt Replacement:** 

No

Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	<b>V</b>			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch	\( \times \)			
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es) 	
Left front	3.2		mm	
Right front	3.2		mm	
Left rear	6.1		mm	
Right rear	5.7		mm	
Spare		Yes		
Suspension				
Suspension performance	~			
Steering performance	<i>'</i>			
Shock absorbers	•			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories	I	Ι		
Head lights	•			
Tail lights Indicators	•			
Dashboard warning lights Wipers (front & rear)	\( \times \)			
Window winder FL				
Window winder FR	<i>V</i>			
Window winder RL				
Window winder RR			1	
Rear view mirrors	~			
Radio (basic test only)	<i>y</i>			
CD (basic test only)	~			
Number of keys	2			
Central locking	·			
Remote locking			·	
Sat. Nav. (basic test only)			·	
			ļ -	

1

Signature: .....

Reversing camera

14 Mar 2019 Inspected by: lan Dunn

Name: .....