

Report ID: 19,122,478 Version: 1 15 Mar 2019 Created:

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2015	Registration:	JNJ26	Reg Expiry:	22 Sep 2019	Engine				
WoF Expiry:	23 Dec 2019	Odometer:	156,543 Kms	Good No:	19122478	Oil level	~			
VIN:	6G1PD5EM1FL134577	Next Service:		Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	unting is mode	for one and miles as	Danta hava nat	heen discontined or	Noise	~			
diagnostic te	s a guide only. Conside sting undertaken. The	vehicle has been	driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	-			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0	S SC S	-161-		Radiator / Hoses (visual)	~			
S = scratch	ALE			NG G	The second	Transmission			1	
D = dent	P SC			ZIN	HIL S	Operation	~			
R = rust PT = paint def	ect NP			$\left(\left \right\rangle \right)$		Noise	~			
C = crack					P	Clutch			~	
P = pin dent	HID				74114	CV joints	~		-	
* = decals	- Alt			-No-		Wheel bearings	~			
SC = stone chi		20		10-	\gg —	Brakes				
W = significant scuffs S						Performance	~			
Da du la a	<u></u>	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
<u>воау ins</u>	pection Comments			. 1		Tyres (lowest observed tread		of tyre	1 2s)	
						Left front	3.		mm	
						Right front	3.		mm	
						Left rear	2		mm	
Conditio	as During Body Insi	pection:	Day			Right rear			mm	
Conditions During Body Inspection: Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			I	
						Operation	~			
Interior Comments						Electrical / Accessories	-		<u> </u>	
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Average					Dashboard warning lights	~			
	A					Wipers (front & rear)	~		1	
Dashboa	ard Average					Window winder FL	~		1	
	I				1	Window winder FR	~		1	
General (<u>Comments</u>					Window winder RL	~		1	
						Window winder RR	~		1	
						Rear view mirrors	~		1	
						Radio (basic test only)	~		1	
						CD (basic test only)	~		1	
						Number of keys	2		1	
Road Con	ditions During Test	Drive [.]	Dry			Central locking	~			
						Remote locking	~		1	
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~	
						-	1		<u> </u>	
Inspected by: Sudhin Ramachandran						Date: 15 Mar 20	19			
I have read	and understood th	is condition g	uide. Name: .			Signature:				