

Report ID: 19,122,506 Version: 1 19 Mar 2019 Created:

Make:	Honda	Model:	Stream	Body Style:	SUV		Pass	Fail	N/A
Year:	2001	Registration:	EUE284	Reg Expiry:	01 Sep 2019	Engine			
WoF Expiry:		Odometer:	240,331 Kms	Good No:	19122506	Oil level	~		
VIN:	7A88GAD0708009473	Next Service:		Service Histor	y: No	Smoke & fumes	~		
			-,			Performance	~		
	port is not a warranty		с I I	<b>D</b>	1 IV	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	s sc w	-0	S SC S SC		SC	Radiator / Hoses (visual)	~		
S = scratch							Transmission		
D = dent						Operation	<b>v</b>		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect III			+		Clutch	•		~
P = pin dent	Ho				JIII —	CV joints	~		V
* = decals	S D PT SC PC			AL-	EINR	Wheel bearings	-		
SC = stone chips									
W = significant scuffs SC W SC S SC						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	7	mm
						Right front	6.	5	mm
						Left rear	4.	5	mm
Conditions During Body Inspection: Dry						Right rear	4.2 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Large engine oil leak Right front shock oil leak						Suspension performance	~		
lighthold	Shock on leak					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
	_					Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking			~
L Engine Timing Mechanismu Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									-
Inspected by: Ian Dunn Date: 15 Mar 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....