

Report ID: 19,123,039 Version: 1 05 Apr 2019 Created:

Make:	Toyota	Model:	Altezza	Body Style:	Sedan]	Pass	Fail	N/A	
Year:	2001	Registration:	EYB696	Reg Expiry:	01 Sep 2019	Engine	1	I	I	
WoF Expiry:	27 Feb 2020	Odometer:	173,700 Kms	Good No:	19123039	Oil level	~			
VIN:	7A8H6390708074164	Next Service:	175492	Service Histor	y: No	Smoke & fumes	V			
						Performance	~			
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	heen discontined or	Noise	V			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:			LS		w	Radiator / Hoses (visual)	~			
S = scratch						Transmission	•			
						Operation 🖌				
R = rust PT = paint defect						Noise	~			
PT = paint defection of C = crack				+	SC	Clutch			~	
P = pin dent	Ho					CV joints	~		•	
*=decals						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC W S S S SC W										
		Note or a	ne defects & blemishes				~			
Body Insp	pection Comments	Note. son	le délects & biennisnes	indy not be disp	layed in the diagram	Hand Brake		. (
Stone chip front window screen						Tyres (lowest observed tread depth of tyres)				
						Left front	-	.5	mm	
						Right front	-	.8	mm	
						Left rear	-	.1	mm	
Conditions During Body Inspection: Dry						5 0.5			mm	
Under Carriage & Under Pennet Inspection Comments						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
No underbo	ody inspection					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments Good						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashh	Average					Wipers (front & rear)	~			
Dashboa						Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1	1		
Road Conditions During Test Drive: Dry						Central locking	~			
			·			Remote locking			~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	1		~	
Inspected by: Melissa Haggerty Date: 05 Apr 2019										

I have read and understood this condition guide.

Name:

Signature: