



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,124,609
Version:	2
Created:	28 Jun 2019

Make:	Lexus	Body Style:	Sedan
Model:	IS250	VIN:	7AT0B00EX19078458
Year:	2008	Odometer:	107,902 Kms
Road Conditions During Test Drive:	Dry		

Electrical			Cooling System			Exterior		
1	Battery	✓	30	Fuel Flap Release	✓	78	Under Carriage	Good
2	Headlights	✓	31	Reversing Camera	✓	79	Sun Roof Operation	<input type="checkbox"/>
3	Tail Lights	✓	32	USB Port	<input type="checkbox"/>	80	Front Windscreen (no chips)	Good
4	High Stop Light	<input type="checkbox"/>	33	Window Lock Switch	<input type="checkbox"/>	81	Back Windscreen (no chips)	Good
5	Front Right Indicators	✓	Transmission and Drive			82	Side Windows (no chips)	Good
6	Front Left Indicators	✓	34	Operation	✓	83	Front Wiper Blades	Good
7	Rear Right Indicators	✓	35	Noise	✓	84	Rear Wiper Blade	Good
8	Rear Left Indicators	✓	36	Clutch	•	85	R/H Mirror	Good
9	Reversing Lights	<input type="checkbox"/>	37	CV Joints	✓	86	L/H Mirror	Good
10	Rear Reflectors	<input type="checkbox"/>	38	Wheel Bearing	✓	87	L/F Guard	Good
11	Hazard Lights	<input type="checkbox"/>	39	Wheel Balance	✓	88	R/F Guard	Good
12	Courtesy Lights	<input type="checkbox"/>	40	Gearbox (Manual)	<input type="checkbox"/>	89	L/H Doors	Good
13	Dashboard Lights	<input type="checkbox"/>	41	Engine Timing	Timing Chain	90	R/H Doors	Good
14	Dashboard Dimmer Switch	<input type="checkbox"/>	42	Evidence of Cam Belt Replacement	Not Applicable	91	L/H Sill	Good
15	Number Plate Light	<input type="checkbox"/>	43	Replaced at (odometer reading)		92	R/H Sill	Good
16	Dashboard Warning Lights	✓	Brakes			93	Boot/Tail Gate	Good
17	Speedo	<input type="checkbox"/>	44	Front Brakes	✓	94	Front Bumper	Good
18	Odometer	<input type="checkbox"/>	45	Rear Brakes	✓	95	Rear Bumper	Good
19	Rev Counter	<input type="checkbox"/>	46	Handbrake	✓	96	Roof	Good
20	Fuel Gauge	<input type="checkbox"/>	Keys and Locking			97	Bonnet	Good
21	Wipers Front/Rear	✓	47	Central Locking	✓	98	Fuel Cap	✓
22	Window Opener FL	✓	48	Remote Locking	✓	99	Mud Flaps	✓
23	Window Opener FR	✓	49	Number of Keys	2	100	WOF	✓
24	Window Opener RL	✓	Engine					
25	Window Opener RR	✓	50	Oil Level	✓			
26	Rear View Mirrors	✓	51	Smokes and Fumes	✓			
27	Radio (Basic Test Only)	✓	52	Performance	✓			
28	CD (Basic Test Only)	✓	53	Noise	✓			
29	Boot Open Switch	✓	54	Starter Motor	✓			
			Suspension					
			55	Coolant Condition	✓			
			56	Performance	✓			
			57	Radiator/Hoses (visual)	✓			
			Wheels and Tyres					
			58	Suspension Performance	✓			
			59	Steering Performance	✓			
			60	Shock Absorbers	✓			
			61	Left Front	6.0			
			62	Right Front	6.0			
			63	Left Rear	7.0			
			64	Right Rear	7.0			
			65	Spare	Yes			
			66	Tools	✓			
			Interior					
			67	AC Operation	✓			
			68	Heater Fan	✓			
			69	Seatbelts	✓			
			70	Horn	✓			
			71	Seat Heaters	<input type="checkbox"/>			
			72	Sun Visors	✓			
			73	Sun Visors Lights/Mirrors	✓			
			74	Seats	driver seat worn			
			75	Carpets	Average			
			76	Panels	Average			
			77	Dashboard	Average			

Turners Certification Key:
 ✓ = Pass
 ✗ = Fail
 • = Not applicable for this vehicle

Inspected by:	Kyle Mills-Brown	Date:	19 Mar 2019
I have read and understood this condition guide:			
Name:		Signature:	