



# Turners Certified Imports 50 Point Check

Report ID: 19,124,609

Version: 1

Created: 19 Mar 2019

**Note: This report is not a warranty**  
 This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Lexus      Body Style: Sedan  
 Model: IS250      Odometer: 107,902 Kms  
 Year: 2008      VIN: 7AT0B00EX19078458

Under Carriage & Under Bonnet Inspection Comments

General Comments

Seats: driver seat worn  
 Carpets: Average  
 Panels: Average  
 Dashboard: Average

Engine Timing Mechanism: Timing Chain  
 Evidence of Cam Belt Replacement: Not Applicable  
 Replaced At (odometer reading):  
 Road Conditions During Test Drive: Dry

| Electrical               |                                     |
|--------------------------|-------------------------------------|
| Battery                  | <input checked="" type="checkbox"/> |
| Head lights              | <input checked="" type="checkbox"/> |
| Tail lights              | <input checked="" type="checkbox"/> |
| Indicators               | <input checked="" type="checkbox"/> |
| Dashboard warning lights | <input checked="" type="checkbox"/> |
| Wipers (front & rear)    | <input checked="" type="checkbox"/> |
| Window winder FL         | <input checked="" type="checkbox"/> |
| Window winder FR         | <input checked="" type="checkbox"/> |
| Window winder RL         | <input checked="" type="checkbox"/> |
| Window winder RR         | <input checked="" type="checkbox"/> |
| Rear view mirrors        | <input checked="" type="checkbox"/> |
| Radio (basic test only)  | <input checked="" type="checkbox"/> |
| CD (basic test only)     | <input checked="" type="checkbox"/> |
| Reversing camera         | <input checked="" type="checkbox"/> |

| Transmission & Drive |                                     |
|----------------------|-------------------------------------|
| Operation            | <input checked="" type="checkbox"/> |
| Noise                | <input checked="" type="checkbox"/> |
| Clutch               | <input type="checkbox"/>            |
| CV joints            | <input checked="" type="checkbox"/> |
| Wheel bearings       | <input checked="" type="checkbox"/> |
| Wheel balance        | <input checked="" type="checkbox"/> |
| Brakes               |                                     |
| Performance          | <input checked="" type="checkbox"/> |
| Hand Brake           | <input checked="" type="checkbox"/> |
| Keys & Locking       |                                     |
| Central locking      | <input checked="" type="checkbox"/> |
| Remote locking       | <input checked="" type="checkbox"/> |
| Number of keys       | <input type="text" value="1"/>      |

| Engine                    |                                     |
|---------------------------|-------------------------------------|
| Oil level                 | <input checked="" type="checkbox"/> |
| Smoke & fumes             | <input checked="" type="checkbox"/> |
| Performance               | <input checked="" type="checkbox"/> |
| Noise                     | <input checked="" type="checkbox"/> |
| Cooling System            |                                     |
| Coolant condition         | <input checked="" type="checkbox"/> |
| Performance               | <input checked="" type="checkbox"/> |
| Radiator / Hoses (visual) | <input checked="" type="checkbox"/> |
| Suspension                |                                     |
| Suspension performance    | <input checked="" type="checkbox"/> |
| Steering performance      | <input checked="" type="checkbox"/> |
| Shock absorbers           | <input checked="" type="checkbox"/> |

| Tyres (lowest observed tread depth) |                                     |
|-------------------------------------|-------------------------------------|
| Left front                          | <input type="text" value="6"/> mm   |
| Right front                         | <input type="text" value="6"/> mm   |
| Left rear                           | <input type="text" value="7"/> mm   |
| Right rear                          | <input type="text" value="7"/> mm   |
| Spare                               | <input type="text" value="Yes"/>    |
| Tools                               | <input checked="" type="checkbox"/> |

| Interior     |                                     |
|--------------|-------------------------------------|
| AC Operation | <input checked="" type="checkbox"/> |
| Heater fan   | <input checked="" type="checkbox"/> |
| Seatbelts    | <input checked="" type="checkbox"/> |
| Horn         | <input checked="" type="checkbox"/> |

**Turners Certified Key**  
 ✓ = Pass      ✗ = Fail  
 • = Not applicable for this vehicle

Inspected by: Kyle Mills-Brown      Date: 19 Mar 2019

I have read and understood this condition guide.      Name: .....      Signature: .....