

## **Basic Vehicle Condition Guide**

Report ID: 19,125,803


Version: 2

Created: 29 Apr 2019

Make: Model: Hyundai Getz **Body Style:** Hatchback Year: 2010 Registration: FLA380 Reg Expiry: 17 Jun 2019 WoF Expiry: **Odometer:** 04 Aug 2019 50,433 Kms **Good No:** 19125803 VIN: KMHBT51DMAU9731( Next Service: 65000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Front wheel drive

Interior Comme	<u>ents</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Xinghui Lin

Evidence of Cam Belt Replacement: No

Kms:

	D	F-:1	NI/A			
	Pass	Fail	N/A			
Engine						
Oil level	<i>-</i>					
Smoke & fumes	\( \times \)					
Performance	<i>'</i>					
Noise	/					
Cooling System						
Coolant condition	~					
Performance	<b>V</b>					
Radiator / Hoses (visual)	/					
Fransmission						
Operation	~					
Noise	~					
Clutch			~			
CV joints	~					
Wheel bearings	~					
Brakes			ı			
Performance	~					
Hand Brake	~					
Tyres (lowest observed tread depth of tyres)						
Left front	4		mm			
Right front	4		mm			
Left rear	4		mm			
Right rear	4		mm			
Spare		Yes				
Suspension						
Suspension performance	~					
Steering performance	✓ ✓					
Shock absorbers	~					
Air Conditioning / Heater						
Operation	~					
Electrical / Accessories						
Head lights	~					
Tail lights	/					
Indicators	> > >					
Dashboard warning lights						
Wipers (front & rear)	~					
Window winder FL	~					
Window winder FR	<b>'</b>					
Window winder RL	<b>v</b>					
Window winder RL Window winder RR	\( \times \) \( \t					
Window winder RL	<b>'</b>					
Window winder RL Window winder RR Rear view mirrors Radio (basic test only)	<b>v</b>					
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	<b>'</b>					
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	<b>v</b>					
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only)	ン ン ン					
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys	<ul><li>✓</li><li>✓</li><li>✓</li><li>✓</li></ul>					
Window winder RL Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking	<ul><li>✓</li><li>✓</li><li>✓</li><li>✓</li><li>✓</li><li>✓</li></ul>					

I have read and understood this condition guide.

Name: .....

Signature: .....

29 Apr 2019