



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,126,513
Version:	2
Created:	05 Sep 2019

Make:	Nissan	Body Style:	Hatchback
Model:	Tiida	VIN:	7AT0DH78X19237453
Year:	2009	Odometer:	105,088 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good						
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good						
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good						
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓	83	Front Wiper Blades	Good	84	Rear Wiper Blade	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓	59	Steering Performance	✓	85	R/H Mirror	Good	86	L/H Mirror	Good				
5	Front Right Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	Wheels and Tyres		87	L/F Guard	Good	88	R/F Guard	Good				
6	Front Left Indicators	✓	36	Clutch	•	61	Left Front	5.0	mm	62	Right Front	5.0	mm	89	L/H Doors	Good				
7	Rear Right Indicators	✓	37	CV Joints	✓	63	Left Rear	4.0	mm	64	Right Rear	4.0	mm	90	R/H Doors	Good				
8	Rear Left Indicators	✓	38	Wheel Bearing	✓	65	Spare	Yes	66	Tools	✓	91	L/H Sill	Good	92	R/H Sill	Good			
9	Reversing Lights	✓	39	Wheel Balance	✓	Interior		67	AC Operation	✓	93	Boot/Tail Gate	Good	94	Front Bumper	Good				
10	Rear Reflectors	✓	40	Gearbox (Manual)	•	68	Heater Fan	✓	69	Seatbelts	✓	95	Rear Bumper	Good	96	Roof	Good			
11	Hazard Lights	✓	41	Engine Timing	Timing Chain	70	Horn	✓	71	Seat Heaters	•	97	Bonnet	Good	98	Fuel Cap	✓			
12	Courtesy Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	99	Mud Flaps	✓	100	WOF	✓			
13	Dashboard Lights	✓	43	Replaced at (odometer reading)		74	Seats	Average	75	Carpets	Average									
14	Dashboard Dimmer Switch	•	Brakes		44	Front Brakes	✓	76	Panels	Average	77	Dashboard	Average							
15	Number Plate Light	✗	45	Rear Brakes	✓	46	Handbrake	✓	Interior		67	AC Operation	✓	68	Heater Fan	✓	69	Seatbelts	✓	
16	Dashboard Warning Lights	✓	47	Central Locking	✓	Keys and Locking		70	Horn	✓	71	Seat Heaters	•	72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	
17	Speedo	✓	48	Remote Locking	•	49	Number of Keys	1	74	Seats	Average	75	Carpets	Average	76	Panels	Average	77	Dashboard	Average
18	Odometer	✓	Engine		50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓	
19	Rev Counter	✓	50	Oil Level	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓			
20	Fuel Gauge	✓	51	Smokes and Fumes	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓						
21	Wipers Front/Rear	✓	52	Performance	✓	53	Noise	✓	54	Starter Motor	✓									
22	Window Opener FL	✓	53	Noise	✓															
23	Window Opener FR	✓	54	Starter Motor	✓															
24	Window Opener RL	✓																		
25	Window Opener RR	✓																		
26	Rear View Mirrors	✓																		
27	Radio (Basic Test Only)	✓																		
28	CD (Basic Test Only)	✓																		
29	Boot Open Switch	✓																		

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:
 ✓ = Pass
 ✗ = Fail
 • = Not applicable for this vehicle

Inspected by:	Greg Morgan	Date:	05 Sep 2019
I have read and understood this condition guide:			
Name:		Signature:	