

Report ID: 19,126,597 Version: 1 21 Mar 2019 Created:

Make:	Fiat	Model:	Grande Punto	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	EHW835	Reg Expiry:	30 Jan 2020	Engine		L	
WoF Expiry:	21 Jan 2020	Odometer:	55,597 Kms	Good No:	19126597	Oil level	~		
VIN:	ZFA19900001281875	Next Service:	65000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	r an additíonal c	narge.	Coolant condition	~		
			S S			Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				215	HIV	Operation	~		
PT = paint defe	ect NP	r I		$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HID				7414	CV joints	~		
* = decals	- Alt			To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	s scums		S		S	Performance	~		
Body Incr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	4.	.5	mm
						Right front	4.	.5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	5 mr		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Sudhin Ramachandran Date: 21 Mar 2019									
Date: 21 Mai 2019									

I have read and understood this condition guide.

Name:

Signature: