

Report ID: 19,138,212 Version: 3 06 May 2019 Created:

Pass Fail N/A

Year:	2005	Registration:	HYB412	Reg Expiry:	19 Jul 2019	Engine			
WoF Expiry:	02 May 2020	Odometer:	209,218 Kms	Good No:	19138212	Oil level	~		
VIN:	7AT0GF0BX14085549	Next Service:	212,800kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	inarge.	Coolant condition	~		
	SC		S SC D			Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent * = decals S D SC S D PT S D S D S D S D S D						Transmission			
						Operation	v		
						Noise	~		
						Clutch			~
						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	S SC S		S D		S	Performance	~		
Rody Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments Child seat anchor point missing						Tyres (lowest observed tread depth of tyres)			
Crinici Scat a	inchor point missing					Left front	2.	.5	mm
						Right front	3.	.0	mm
						Left rear	8.	.0	mm
Conditions During Body Inspection: Dry						Right rear	8.0		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Poor					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~	-	
General Comments						Window winder RL	~		
						Window winder RR	~	-	
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	<u> </u>	1
Road Conditions During Test Drive: Dry						Central locking	-		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
L						-	1	1	1
Inspected by: Ca Thach Date: 23 Apr 2019									

I have read and understood this condition guide.

Name:

Signature: