



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,139,045
Version:	2
Created:	06 Sep 2019

Make:	Honda	Body Style:	SUV
Model:	Stream	VIN:	7AT08GADX19083245
Year:	2008	Odometer:	120,933 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	78	Under Carriage	Good	
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	79	Sun Roof Operation	•	
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		80	Front Windscreen (no chips)	Good		
4	High Stop Light	✓	Transmission and Drive		58	Suspension Performance	✓	81	Back Windscreen (no chips)	Good		
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	82	Side Windows (no chips)	Good	
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	83	Front Wiper Blades	Good	
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		84	Rear Wiper Blade	Good		
8	Rear Left Indicators	✓	37	CV Joints	✓	61	Left Front	7	mm	85	R/H Mirror	Good
9	Reversing Lights	✓	38	Wheel Bearing	✓	62	Right Front	7	mm	86	L/H Mirror	Good
10	Rear Reflectors	✓	39	Wheel Balance	✓	63	Left Rear	7	mm	87	L/F Guard	Good
11	Hazard Lights	✓	40	Gearbox (Manual)	•	64	Right Rear	7	mm	88	R/F Guard	Good
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	65	Spare	Yes	89	L/H Doors	Good	
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	66	Tools	✓	90	R/H Doors	Good	
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		Interior		91	L/H Sill	Good		
15	Number Plate Light	✓	Brakes		67	AC Operation	✓	92	R/H Sill	Good		
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	68	Heater Fan	✓	93	Boot/Tail Gate	Good	
17	Speedo	✓	45	Rear Brakes	✓	69	Seatbelts	✓	94	Front Bumper	Good	
18	Odometer	✓	46	Handbrake	✓	70	Horn	✓	95	Rear Bumper	Good	
19	Rev Counter	✓	Keys and Locking		71	Seat Heaters	•	96	Roof	Good		
20	Fuel Gauge	✓	47	Central Locking	✓	72	Sun Visors	✓	97	Bonnet	Good	
21	Wipers Front/Rear	✓	48	Remote Locking	✓	73	Sun Visors Lights/Mirrors	✓	98	Fuel Cap	✓	
22	Window Opener FL	✓	49	Number of Keys	2	74	Seats	Average	99	Mud Flaps	✓	
23	Window Opener FR	✓	Engine		75	Carpets	Average	100	WOF	✓		
24	Window Opener RL	✓	50	Oil Level	✓	76	Panels	Average				
25	Window Opener RR	✓	51	Smokes and Fumes	✓	77	Dashboard	Average				
26	Rear View Mirrors	✓	52	Performance	✓							
27	Radio (Basic Test Only)	✓	53	Noise	✓							
28	CD (Basic Test Only)	✓	54	Starter Motor	✓							
29	Boot Open Switch	✓										

**Turners Certification Key:**

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

#### Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Kyle Mills-Brown	Date:	06 Sep 2019
---------------	------------------	-------	-------------

**I have read and understood this condition guide:**

Name:		Signature:	
-------	--	------------	--