

Basic Vehicle Condition Guide

Report ID: 56,526

Version: 2


Created: 17 Apr 2019

Pass Fail N/A

Make: Model: V50 Volvo **Body Style:** SUV Year: 2006 Registration: HKA344 Reg Expiry: 06 Jul 2019 WoF Expiry: **Odometer:** 08 Apr 2020 89,636 Kms **Good No:** 19139803 VIN: YV1MW665972282047 Next Service: Due **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Hood lining coming down

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Average			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 57,000

F.,			
Engine			
Oil level	~		
Smoke & fumes	V V		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	V V		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	l :s)
Left front		5.0	mm
Right front	5.0		mm
Left rear	4.0		mm
Right rear			mm
Spare	4	Yes	
Suspension		163	
Suspension performance	•		
Steering performance	•		
Shock absorbers	•		
Air Conditioning / Heater			
Operation	•		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	1	-
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

Signature:

Inspected by: Scott Date: 26 Mar 2019

Name: