

Basic Vehicle Condition Guide

Report ID: 19,140,420

Version: 2

Engine


Oil level

27 Jun 2019 Created:

Fail

N/A

Make: Volkswagen Model: Beetle **Body Style:** Hatchback Year: 2008 Registration: JDJ728 **Reg Expiry:** 27 Jan 2020 WoF Expiry: 23 Mar 2020 **Odometer:** 70,793 Kms Good No: 19140420



I have read and understood this condition guide.

lan Dunn

Inspected by:

	Sat. Nav. (basic test only)	~							
Kms:	Reversing camera	~							
Date: 22 Mar 2019									
Name:	Signature:								

v	IN: WVWZZZ90	ZZ8M55402 Next Service: 80,000	Service History: Yes	Smoke & fumes	~		
_				Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or				Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.			Cooling System				
a	Tull mechanical mspecti	on phor to purchase and this can be arranged	i loi all'additional charge.	Coolant condition	~		
_	SC	SC		Performance	~		
	Key.		5(0)	Radiator / Hoses (visual)	~		
			Transmission				
	= rust SC		SC	Operation	~		
P ⁻	T = paint defect	NIMI II II		Noise	~		
C	= crack			Clutch			~
	= pin dent			CV joints	~		
	= decals C = stone chips			Wheel bearings	~		
	/ = significant scuffs		$\Xi(Q)$	Brakes	•		
-	W	S		Performance	~		
	Body Inspection Co	Note: some defects & blemis	hes may not be displayed in the diagram	Hand Brake	~		
	Hood liner loose			Tyres (lowest observed tread	depth	epth of tyres)	
				Left front	6.7	7	mm
				Right front	6.3	3	mm
_				Left rear	6.6	5	mm
	Conditions During	Body Inspection: Dry		Right rear	7.2	2	mm
			Spare				
	<u>Under Carriage & U</u>	nder Bonnet Inspection Comments		Suspension			
				Suspension performance	•		
				Steering performance	•		
				Shock absorbers	•		
				Air Conditioning / Heater			
_				Operation	•		
	Interior Comments			Electrical / Accessories			
	Seats	Good		Head lights	•		
	Carpets	Good		Tail lights	•		
	carpets			Indicators	~		
	Panels	Good		Dashboard warning lights	•		
	Dashboard	Good		Wipers (front & rear)	~		
	Dasiiboaid			Window winder FL	•		
_	6 16 .			Window winder FR	~		
	General Comments	<u>i</u>		Window winder RL			~
				Window winder RR			~
				Rear view mirrors	~		
				Radio (basic test only)	•		
				CD (basic test only)	•		
_				Number of keys	2		
	Road Conditions Du	ıring Test Drive: Dry		Central locking	~		
_	Engino Timina Mad	hanism: Cambalt		Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms: Sat. Nav. (basic test only) Reversing camera					~		
	Evidence of Cam Be	lt Replacement: No	Kms:	Poversing camera			