



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,140,496
Version:	2
Created:	06 Sep 2019

Make:	Nissan	Body Style:	Wagon
Model:	Wingroad	VIN:	7AT0DH5GX19016103
Year:	2007	Odometer:	73,619 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		55	Coolant Condition	✓	Exterior		78	Under Carriage	Good			
1	Battery	✓	31	Reversing Camera	•	56	Performance	✓	79	Sun Roof Operation	•	80	Front Windscreen (no chips)	Good			
2	Headlights	✓	32	USB Port	•	57	Radiator/Hoses (visual)	✓	81	Back Windscreen (no chips)	Good	82	Side Windows (no chips)	Good			
3	Tail Lights	✓	33	Window Lock Switch	✓	Suspension		58	Suspension Performance	✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td>	83	Front Wiper Blades	Good				
4	High Stop Light	✓	Transmission and Drive		34	Operation	✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th>	59	Steering Performance	✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>	84	Rear Wiper Blade	Good				
5	Front Right Indicators	✓	35	Noise	✓ <td>36</td> <td>Clutch</td> <td>•</td> <td>60</td> <td>Shock Absorbers</td> <th>✓<td>85</td><td>R/H Mirror</td><td>Good</td></th>	36	Clutch	•	60	Shock Absorbers	✓ <td>85</td> <td>R/H Mirror</td> <td>Good</td>	85	R/H Mirror	Good			
6	Front Left Indicators	✓	37	CV Joints	✓ <th colspan="2">Wheels and Tyres</th> <td>61</td> <td>Left Front</td> <td>5</td> <td>mm</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td>	Wheels and Tyres		61	Left Front	5	mm	86	L/H Mirror	Good			
7	Rear Right Indicators	✓	38	Wheel Bearing	✓ <td>62</td> <td>Right Front</td> <td>6</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>6</td> <td>mm</td> <td>87</td> <td>L/F Guard</td> <td>Good</td>	62	Right Front	6	mm	63	Left Rear	6	mm	87	L/F Guard	Good	
8	Rear Left Indicators	✓	39	Wheel Balance	✓ <td>64</td> <td>Right Rear</td> <td>6</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>88</td> <td>R/F Guard</td> <td>Good</td>	64	Right Rear	6	mm	65	Spare	Yes	88	R/F Guard	Good		
9	Reversing Lights	✓	40	Gearbox (Manual)	•	66	Tools	✓	67	AC Operation	✓ <td>89</td> <td>L/H Doors</td> <td>Good</td>	89	L/H Doors	Good			
10	Rear Reflectors	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>90</td><td>R/H Doors</td><td>Good</td></th>	69	Seatbelts	✓ <td>90</td> <td>R/H Doors</td> <td>Good</td>	90	R/H Doors	Good			
11	Hazard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	70	Horn	✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>91</td> <td>L/H Sill</td> <td>Good</td>	71	Seat Heaters	•	91	L/H Sill	Good			
12	Courtesy Lights	✓	43	Replaced at (odometer reading)		72	Sun Visors	✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>92</td><td>R/H Sill</td><td>Good</td></th>	73	Sun Visors Lights/Mirrors	✓ <td>92</td> <td>R/H Sill</td> <td>Good</td>	92	R/H Sill	Good			
13	Dashboard Lights	✓	Brakes		44	Front Brakes	✓ <td>74</td> <td>Seats</td> <td>Average</td> <td>75</td> <td>Carpets</td> <td>Average</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td>	74	Seats	Average	75	Carpets	Average	93	Boot/Tail Gate	Good	
14	Dashboard Dimmer Switch	•	45	Rear Brakes	✓ <td>46</td> <td>Handbrake</td> <th>✓<td>76</td><td>Panels</td><td>Average</td><td>77</td><td>Dashboard</td><td>Average</td><td>94</td><td>Front Bumper</td><td>Good</td></th>	46	Handbrake	✓ <td>76</td> <td>Panels</td> <td>Average</td> <td>77</td> <td>Dashboard</td> <td>Average</td> <td>94</td> <td>Front Bumper</td> <td>Good</td>	76	Panels	Average	77	Dashboard	Average	94	Front Bumper	Good
15	Number Plate Light	✓	Keys and Locking		47	Central Locking	✓ <td>78</td> <td>Fuel Cap</td> <th>✓<td>79</td><td>Mud Flaps</td><th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th></th>	78	Fuel Cap	✓ <td>79</td> <td>Mud Flaps</td> <th>✓<td>95</td><td>Rear Bumper</td><td>Good</td></th>	79	Mud Flaps	✓ <td>95</td> <td>Rear Bumper</td> <td>Good</td>	95	Rear Bumper	Good	
16	Dashboard Warning Lights	✓	48	Remote Locking	✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>100</td> <td>WOF</td> <th>✓</th> <td></td> <td></td> <td></td> <td></td> <td></td>	49	Number of Keys	2	100	WOF	✓						
17	Speedo	✓	Engine		50	Oil Level	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>										
18	Odometer	✓	51	Smokes and Fumes	✓ <td>52</td> <td>Performance</td> <th>✓<td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th>	52	Performance	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
19	Rev Counter	✓	53	Noise	✓ <td>54</td> <td>Starter Motor</td> <th>✓<td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></th>	54	Starter Motor	✓ <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
20	Fuel Gauge	✓															
21	Wipers Front/Rear	✓															
22	Window Opener FL	✓															
23	Window Opener FR	✓															
24	Window Opener RL	✓															
25	Window Opener RR	✓															
26	Rear View Mirrors	✓															
27	Radio (Basic Test Only)	✓															
28	CD (Basic Test Only)	✓															
29	Boot Open Switch	✓															

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:
 ✓ = Pass
 ✗ = Fail
 • = Not applicable for this vehicle

Inspected by:	Kyle Mills-Brown	Date:	06 Sep 2019
I have read and understood this condition guide:			
Name:		Signature:	