

Report ID: 19,141,385 Version: 5 09 May 2019 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	FUG972	Reg Expiry:	13 Dec 2019	Engine	1		1
WoF Expiry:	22 Sep 2019	Odometer:	109,603 Kms	Good No:	19141385	Oil level	~		
VIN:	JM0GH105200211901	Next Service:	118000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
	S W		SD SW		S W	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S PT C SC			10	S D PT	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack					RSC	Clutch			~
P = pin dent						CV joints	~		
* = decals SD NSC S						Wheel bearings	<		
W = significant scuffs						Brakes			
	S W		S W S D		S D	Performance	٢		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Chip windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front	7.0 mm		mm
						Right front	7.	.0	mm
						Left rear	4.	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
front seat worn marks rear seats						Electrical / Accessories			
Seats		,				Head lights	~		
Carpets	rear left ca	rpet marks				Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	ard Average					Wipers (front & rear)	~		
						Window winder FL	~		
General Comments						Window winder FR	<b>v</b>		
						Window winder RL Window winder RR	<b>v</b>		
							~		
						Rear view mirrors	<b>v</b>		
						Radio (basic test only)	<b>v</b>		
						CD (basic test only) Number of keys			
Dead Canditions During Test Driver						Central locking	2		
Road Conditions During Test Drive: Dry						-	<b>~</b>		
Engine Timing Mechanism:     Timing Chain     Remote locking       Sat. Nav. (basic test only)     Sat. Nav. (basic test only)							~		
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera									~ ~
Inspected by: Kyle Mills-Brown Date: 01 Apr 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....