

Basic Vehicle Condition Guide

Report ID: 19,142,354


Version: 2

Created: 04 Apr 2019

Make: Model: Nissan Lafesta **Body Style:** SUV Year: 2005 Registration: HKZ374 Reg Expiry: 20 Jul 2019 WoF Expiry: **Odometer: Good No:** 05 Dec 2019 158,921 Kms 19142354 VIN: 7AT0DH7DX14008772 Next Service: 166424 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

No rear seats. Stone chips front screen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Average		
Carpets	Good		
Panels	Average		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

26 Mar 2019 Inspected by: Date:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	V			
Radiator / Hoses (visual)	~			
Transmission	•		•	
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes		1	1	
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	d depth	of tyre	es)	
Left front	2	.0	mm	
Right front	2.0		mm	
Left rear	3.0		mm	
Right rear	4.0		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation 🗸				
Electrical / Accessories				
Head lights	V			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	V V V V V			
Window winder FL	<i>y</i>			
Window winder FR	1/			
Window winder RL	1/			
Window winder RR	1/			
Rear view mirrors	~			
Radio (basic test only)	<i>v</i>			
CD (basic test only)		.,		
<u> </u>	2	<i>'</i>		
Number of keys	2			
Central locking	•			
Remote locking				
Sat. Nav. (basic test only)			<i>V</i>	
Reversing camera			~	

I have read and understood this condition guide.

Name:

Signature: