

Report ID: 19,144,640 Version: 3 06 May 2019 Created:

Make:	Hyundai	Model:	Sonata	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2006	Registration:	DLQ659	Reg Expiry:	01 Apr 2019	Engine				
WoF Expiry:	14 May 2020	Odometer:	113,482 Kms	Good No:	19144640	Oil level	~			
VIN:	, KMHET41CR6A239889	Next Service:	127000	Service Histor	y: Yes	Smoke & fumes	~			
					-	Performance	~			
	port is not a warranty		6	Danta harra nat	harry discovered and an	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	SC	-0	SR SR	-161-	s	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent						Operation	~			
R = rust PT = paint def	ect NP			\prod		Noise	~			
C = crack				+		Clutch	•		~	
P = pin dent					세비	CV joints	~			
* = decals	sc 916			- Jul	ELE SP	Wheel bearings	V			
SC = stone chips						Brakes				
W = significan	t scuffs		S P		S D R P	Performance	~			
Dedulae		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body inspection Comments						Tyres (lowest observed tread depth of tyres)			es)	
Stone chips on windscreen Central locking switch not working									mm	
						Right front	3.	-	mm	
						Left rear	3.		mm	
Conditions During Body Inspection: Dry						Right rear	3.0 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
Shock							~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
<u></u>	Good					Tail lights	~			
Carpets	0000					Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, crack on d	ash board				Wipers (front & rear)	~			
Dashboa	ird					Window winder FL	~			
	I					Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Bobby Zhong Date: 30 Apr 2019										

I have read and understood this condition guide.

Name:

Signature: