



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| | |
|------------|-------------|
| Report ID: | 19,145,375 |
| Version: | 2 |
| Created: | 09 Sep 2019 |

| | | | |
|------------------------------------|--------|-------------|-------------------|
| Make: | Nissan | Body Style: | Hatchback |
| Model: | Note | VIN: | 7AT0DH79X19496872 |
| Year: | 2010 | Odometer: | 86,383 Kms |
| Road Conditions During Test Drive: | Dry | | |

| Electrical | | 30 | Fuel Flap Release | ✓ | Cooling System | | 55 | Coolant Condition | ✓ | Exterior | | 78 | Under Carriage | Good | | | |
|------------|--------------------------|----|------------------------|----------------------------------|---|------------------|---|--|------------------------|---|-----------|----------------------------|------------------|------------|------------|--------------|------|
| 1 | Battery | ✓ | 31 | Reversing Camera | ✓ | 56 | Performance | ✓ | 79 | Sun Roof Operation | | • | | | | | |
| 2 | Headlights | ✓ | 32 | USB Port | • | 57 | Radiator/Hoses (visual) | ✓ | 80 | Front Windscreen (no chips) | Good | | | | | | |
| 3 | Tail Lights | ✓ | 33 | Window Lock Switch | ✓ | Suspension | | 58 | Suspension Performance | ✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td> | 81 | Back Windscreen (no chips) | Good | | | | |
| 4 | High Stop Light | ✓ | Transmission and Drive | | 34 | Operation | ✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th> | 59 | Steering Performance | ✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> | 82 | Side Windows (no chips) | Good | | | | |
| 5 | Front Right Indicators | ✓ | 35 | Noise | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th> | 60 | Shock Absorbers | ✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td> | 83 | Front Wiper Blades | Good | | | | | | |
| 6 | Front Left Indicators | ✓ | 36 | Clutch | • | Wheels and Tyres | | 61 | Left Front | 6 | mm | 84 | Rear Wiper Blade | Good | | | |
| 7 | Rear Right Indicators | ✓ | 37 | CV Joints | ✓ <td>62</td> <td>Right Front</td> <td>5</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>6</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td> | 62 | Right Front | 5 | mm | 63 | Left Rear | 6 | mm | 85 | R/H Mirror | Good | |
| 8 | Rear Left Indicators | ✓ | 38 | Wheel Bearing | ✓ <td>64</td> <td>Right Rear</td> <td>6</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>Yes</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td> | 64 | Right Rear | 6 | mm | 65 | Spare | Yes | 86 | L/H Mirror | Good | | |
| 9 | Reversing Lights | ✓ | 39 | Wheel Balance | ✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td> <td>88</td> <td>R/F Guard</td> <td>Good</td> | 66 | Tools | ✓ | 87 | L/F Guard | Good | 88 | R/F Guard | Good | | | |
| 10 | Rear Reflectors | ✓ | 40 | Gearbox (Manual) | • | Interior | | 67 | AC Operation | ✓ | 89 | L/H Doors | Good | 90 | R/H Doors | Good | |
| 11 | Hazard Lights | ✓ | 41 | Engine Timing | Timing Chain | 68 | Heater Fan | ✓ | 69 | Seatbelts | ✓ | 91 | L/H Sill | Good | 92 | R/H Sill | Good |
| 12 | Courtesy Lights | ✓ | 42 | Evidence of Cam Belt Replacement | Not Applicable | 70 | Horn | ✓ | 71 | Seat Heaters | • | 93 | Boot/Tail Gate | Good | 94 | Front Bumper | Good |
| 13 | Dashboard Lights | ✓ | 43 | Replaced at (odometer reading) | | 72 | Sun Visors | ✓ | 73 | Sun Visors Lights/Mirrors | ✓ | 95 | Rear Bumper | Good | 96 | Roof | Good |
| 14 | Dashboard Dimmer Switch | • | Brakes | | 44 | Front Brakes | ✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>75</td> <td>Carpets</td> <td>Good</td> <td>76</td> <td>Panels</td> <td>Good</td> | 74 | Seats | Good | 75 | Carpets | Good | 76 | Panels | Good | |
| 15 | Number Plate Light | ✓ | 45 | Rear Brakes | ✓ <td>46</td> <td>Handbrake</td> <th>✓<td>77</td><td>Dashboard</td><td>Good</td><td>78</td><td>WOF</td><th>✓</th></th> | 46 | Handbrake | ✓ <td>77</td> <td>Dashboard</td> <td>Good</td> <td>78</td> <td>WOF</td> <th>✓</th> | 77 | Dashboard | Good | 78 | WOF | ✓ | | | |
| 16 | Dashboard Warning Lights | ✓ | Keys and Locking | | 47 | Central Locking | ✓ <td>79</td> <td>Fuel Cap</td> <th>✓</th> <td>80</td> <td>Mud Flaps</td> <th>✓</th> | 79 | Fuel Cap | ✓ | 80 | Mud Flaps | ✓ | | | | |
| 17 | Speedo | ✓ | 48 | Remote Locking | ✓ <td>49</td> <td>Number of Keys</td> <td>1</td> <td>81</td> <td>WOF</td> <th>✓</th> | 49 | Number of Keys | 1 | 81 | WOF | ✓ | | | | | | |
| 18 | Odometer | ✓ | Engine | | 50 | Oil Level | ✓ <td>82</td> <td>Starter Motor</td> <th>✓</th> | 82 | Starter Motor | ✓ | | | | | | | |
| 19 | Rev Counter | ✓ | 51 | Smokes and Fumes | ✓ <td>52</td> <td>Performance</td> <th>✓</th> | 52 | Performance | ✓ | | | | | | | | | |
| 20 | Fuel Gauge | ✓ | 53 | Noise | ✓ | | | | | | | | | | | | |
| 21 | Wipers Front/Rear | ✓ | 54 | Starter Motor | ✓ | | | | | | | | | | | | |
| 22 | Window Opener FL | ✓ | | | | | | | | | | | | | | | |
| 23 | Window Opener FR | ✓ | | | | | | | | | | | | | | | |
| 24 | Window Opener RL | ✓ | | | | | | | | | | | | | | | |
| 25 | Window Opener RR | ✓ | | | | | | | | | | | | | | | |
| 26 | Rear View Mirrors | ✓ | | | | | | | | | | | | | | | |
| 27 | Radio (Basic Test Only) | ✓ | | | | | | | | | | | | | | | |
| 28 | CD (Basic Test Only) | ✓ | | | | | | | | | | | | | | | |
| 29 | Boot Open Switch | ✓ | | | | | | | | | | | | | | | |

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

| | | | |
|---------------|---------------|-------|-------------|
| Inspected by: | Neil Honeyman | Date: | 09 Sep 2019 |
|---------------|---------------|-------|-------------|

I have read and understood this condition guide:

| | | | |
|-------|--|------------|--|
| Name: | | Signature: | |
|-------|--|------------|--|