

Report ID: 19,146,501 Version: 2 18 Apr 2019 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A	
Year:	2004	<b>Registration:</b>	CEE37	Reg Expiry:	01 Oct 2019	Engine			L	
WoF Expiry:	18 Feb 2020	Odometer:	226,717 Kms	Good No:	19146501	Oil level	~			
VIN:	6FPAAAJGAT4D42813	Next Service:	236000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	charge.	Coolant condition	~			
	SC					Performance	~			
Key:	Lise (	-0	SC	-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	SC D			715	SC	Operation	~			
PT = paint defe				$\left( \left  \left( \right) \right\rangle \right)$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIP				2414	CV joints	~			
* = decals	sc 916			The second		Wheel bearings	~			
SC = stone chips						Brakes				
W = significan	t scuffs SC		SC			Performance	~			
Body Incr	portion Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~			
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			es)	
								mm		
						Right front	5.	0	mm	
						Left rear	5.		mm	
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Engine oil le	eak from rear of engine					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Poor					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Con	Road Conditions During Test Drive: Dry						~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Increast-	Inspected by: Dion Mair Date: 29 Mar 2019									
Date: 29 Midi 2019										

I have read and understood this condition guide.

Name: .....

Signature: .....