

Report ID: 19,147,050 Version: 1 31 Mar 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2017	Registration:	KUY710	Reg Expiry:	28 Sep 2019	Engine			
WoF Expiry:	29 Sep 2020	Odometer:	45,384 Kms	Good No:	19147050	Oil level	~		
VIN:	WF0EXXWPCEHJ7216	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	sc	-0	ls		sc	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			To	Transmission	V		
D = dent	sc			The	BIDS	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect			+		Clutch			~
P = pin dent	Ho				JUII —	CV joints	~		~
* = decals	sc pp			AL-		Wheel bearings	-		
SC = stone chips							Wheel bearings		
W = significant scuffs W P S D									1
		Notorer	ne defects & blemishes			Performance Hand Brake	<b>v</b>		
Body Ins	pection Comments	Note: son	ie delects & blemisnes	may not be disp	hayed in the diagram			<u> </u>	Ļ
Stone chip on front windscreen						Tyres (lowest observed tread depth of tyres)			
						Left front	4	1	mm
						Right front		1	mm
						Left rear	1	.6	mm
Conditions During Body Inspection: Dry						Right rear	1	1.6 mm	
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
Under Ca	irriage & Under Bor	inet inspectio	on Comments			Suspension	1		1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carnota	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ard					Window winder FL	~		
						Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera	~		
L							L .		1
Inspected by: Mathew Varghese Date: 31 Mar 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....