

Report ID: 19,149,665 Version: 1 Created: 03 Apr 2019

Make:	Mitsubishi	Model:	Mirage	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2002	<b>Registration:</b>	AMQ977	<b>Reg Expiry:</b>	14 Jul 2019	Engine			
WoF Expiry:	30 Jan 2020	Odometer:	76,904 Kms	Good No:	19149665	Oil level	~		
VIN:	XMDLRDG3A2F03022	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	S SC S		S P SC W S D	S	S D SC	Performance	~		
Key:	330 13	-0	3P3CW 3D		3030	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	S SC			715	SD SD	Operation	~		
PT = paint defe	ect NP	FI		$\left( \left  \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	HIC				74114	CV joints	~		
* = decals	ssc 916			-Jul-	BID SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC S SC						Performance 🖌			
Declar		Note: son	ne defects & blemishes	may not be disc	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-		
Stone chips in the windscreen ,						Left front	2		 
						Right front	3		mm
						Left rear	2		mm
Canalitian	- Durin a De du la s		2			Right rear			 mm
Conditions During Body Inspection: Dry						Spare	-		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Yes			
						Suspension performance			<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
Interior Comments						Operation Electrical / Accessories		~	
	drivers sea	at ripped ,				Head lights			<u> </u>
Seats						-	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		<u> </u>
<u>General Comments</u> Check engine light is on ,pulls to the left when driving also makes a noise from LF area,					Window winder RL	~		<u> </u>	
ea.engi						Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		-
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking			~
						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	No	Kms:		Reversing camera	~		
Inspected by: Donovan Matara						Date: 03 Apr 2019			
inspected	a sy. Bonovan watar	~					. ,		
I have read a	and understood th	is condition c	guide. Name:			Signature:			