



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,150,271
Version:	2
Created:	10 Sep 2019

Make:	Mazda	Body Style:	Hatchback
Model:	Axela	VIN:	7AT0C13JX19103199
Year:	2014	Odometer:	75,421 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30 Fuel Flap Release		Cooling System		Exterior					
1	Battery	✓	✓	55	Coolant Condition	✓	78 Under Carriage	Good			
2	Headlights	✓	✓	56	Performance	✓	79 Sun Roof Operation	✓			
3	Tail Lights	✓	✓	57	Radiator/Hoses (visual)	✓	80 Front Windscreen (no chips)	Good			
4	High Stop Light	✓	✓	Transmission and Drive		Suspension		81 Back Windscreen (no chips)	Good		
5	Front Right Indicators	✓	✓	34	Operation	✓	82 Side Windows (no chips)	Good			
6	Front Left Indicators	✓	✓	35	Noise	✓	83 Front Wiper Blades	Good			
7	Rear Right Indicators	✓	✓	36	Clutch	•	84 Rear Wiper Blade	Good			
8	Rear Left Indicators	✓	✓	37	CV Joints	✓	Wheels and Tyres				
9	Reversing Lights	✓	✓	38	Wheel Bearing	✓	61 Left Front	5 mm	85 R/H Mirror	Good	
10	Rear Reflectors	✓	✓	39	Wheel Balance	✓	62 Right Front	5 mm	86 L/H Mirror	Good	
11	Hazard Lights	✓	✓	40	Gearbox (Manual)	•	63 Left Rear	6 mm	87 L/F Guard	Good	
12	Courtesy Lights	✓	✓	41	Engine Timing	Timing Chain	64 Right Rear	6 mm	88 R/F Guard	Good	
13	Dashboard Lights	✓	✓	42	Evidence of Cam Belt Replacement	Not Applicable	65 Spare	Yes	89 L/H Doors	Good	
14	Dashboard Dimmer Switch	✓	✓	43	Replaced at (odometer reading)		66 Tools	✓	90 R/H Doors	Good	
15	Number Plate Light	✓	✓	Brakes		Interior		91 L/H Sill	Good	92 R/H Sill	Good
16	Dashboard Warning Lights	✓	✓	44	Front Brakes	✓	67 AC Operation	✓	93 Boot/Tail Gate	Good	
17	Speedo	✓	✓	45	Rear Brakes	✓	68 Heater Fan	✓	94 Front Bumper	Good	
18	Odometer	✓	✓	46	Handbrake	✓	69 Seatbelts	✓	95 Rear Bumper	Good	
19	Rev Counter	✓	✓	Keys and Locking				70 Horn	✓	96 Roof	Good
20	Fuel Gauge	✓	✓	47	Central Locking	✓	71 Seat Heaters	✓	97 Bonnet	Good	
21	Wipers Front/Rear	✓	✓	48	Remote Locking	✓	72 Sun Visors	✓	98 Fuel Cap	✓	
22	Window Opener FL	✓	✓	49	Number of Keys	1	73 Sun Visors Lights/Mirrors	✓	99 Mud Flaps	✓	
23	Window Opener FR	✓	✓	Engine				74 Seats	Good	100 WOF	✓
24	Window Opener RL	✓	✓	50	Oil Level	✓	75 Carpets	Good			
25	Window Opener RR	✓	✓	51	Smokes and Fumes	✓	76 Panels	Good			
26	Rear View Mirrors	✓	✓	52	Performance	✓	77 Dashboard	Good			
27	Radio (Basic Test Only)	✓	✓	53	Noise	✓					
28	CD (Basic Test Only)	✓	✓	54	Starter Motor	✓					
29	Boot Open Switch	✓	✓								

Turners Certification Key:

- ✓ = Pass
- × = Fail
- = Not applicable for this vehicle

Inspected by:	Neil Honeyman	Date:	10 Sep 2019
---------------	---------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--