

Basic Vehicle Condition Guide

Report ID: 19,150,575


Version: 7

Created: 08 Jul 2019

Make: Model: Honda Elysion **Body Style:** SUV Year: 2004 Registration: KSN167 Reg Expiry: 20 Sep 2019 WoF Expiry: **Odometer: Good No:** 14 Nov 2019 132,305 Kms 19150575 VIN: 7AT08GBPX17001628 Next Service: 137325 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Right side dash compartment lid missing. Stone chips front screen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

light Oil leak

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Brian Hill

Evidence of Cam Belt Replacement: No Kms:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	V		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	3.0		mm
Right front	4.0		mm
Left rear	5.0		mm
Right rear	4.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	\(\sigma \)		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Poversing camera			

Reversing camera

02 Apr 2019

Signature: