

Report ID: 19,150,974 Version: 1 02 Apr 2019 Created:

| Make:  | Daihatsu  | Model:               | Sirion                 | Body Style:         | Hatchback             |  | Pass | Fail     | N/A |
|--|---|----------------------|------------------------|---------------------|-----------------------|--|------|----------|-----|
| Year:  | 2008  | <b>Registration:</b> | EPN586                 | <b>Reg Expiry:</b>  | 30 Apr 2019           | Engine                                       | 1]   |          |     |
| WoF Expiry:  | 24 Jan 2020                                     | Odometer:            | 80,908 Kms             | Good No:            | 19150974              | Oil level                                    | ~    |          |     |
| VIN:   | JDAM301S001073546                               | Next Service:        | 90800                  | Service Histor      | <b>y:</b> No          | Smoke & fumes                                | ~    |          |     |
|  |   |                      |                        |                     |                       | Performance                                  | ~    |          |     |
|  | port is not a warranty<br>a quide only. Conside | eration is made      | for age and mileage.   | . Parts have not    | been dismantled or    | Noise  | ~    |          |     |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |   |                      |                        |                     |                       | Cooling System                               |      |          |     |
| a full mechan  | ical inspection prior to                        | purchase and u       | his can be arranged to | or an additional of | .narge.               | Coolant condition                            | ~    |          |     |
|  | S   |                      | S S                    |                     | S                     | Performance                                  | ~    |          |     |
| <b>Key:</b><br>S = scratch   |   | =(0)                 |                        | 5(0)-               |                       | Radiator / Hoses (visual)                    | ~    |          |     |
|  |   |                      |                        |                     |                       | Transmission                                 |      |          |     |
| R = rust   | S D PT SC                                       |                      |                        | 10                  | HIL S                 | Operation                                    | ~    |          |     |
| PT = paint def   | ect NP  |                      |                        |                     |                       | Noise  | ~    |          |     |
| C = crack  |   |                      |                        |                     | R PT SC               | Clutch                                       | ~    |          |     |
| P = pin dent   | R SC DE   |                      |                        |                     | 241 <u>16</u>         | CV joints                                    | ~    |          |     |
| * = decals   |   | 10                   |                        | 10                  | SPT SPT               | Wheel bearings                               | ~    |          |     |
| SC = stone chips<br>W = significant scuffs   |   |                      |                        |                     |                       | Brakes                                       |      |          |     |
|  | S W   |                      | S S P                  | W                   | D                     | Performance                                  | ~    |          |     |
| Body Insp  | pection Comments                                | Note: son            | ne defects & blemishes | may not be disp     | blayed in the diagram | Hand Brake                                   | ~    |          |     |
| <u></u>  |   |                      |                        |                     |                       | Tyres (lowest observed tread depth of tyres) |      |          |     |
|  |   |                      |                        |                     |                       | Left front                                   | 6 mm |          | mm  |
|  |   |                      |                        |                     |                       | Right front                                  | 6 mm |          | mm  |
|  |   |                      |                        |                     |                       | Left rear                                    | 7    | ,        | mm  |
| Conditions During Body Inspection: Dry   |   |                      |                        |                     |                       | Right rear                                   | 6 mm |          |     |
|  |   |                      |                        |                     |                       | Spare  | Yes  |          |     |
| Under Carriage & Under Bonnet Inspection Comments  |   |                      |                        |                     |                       | Suspension                                   |      |          |     |
|  |   |                      |                        |                     |                       | Suspension performance                       | ~    |          |     |
|  |   |                      |                        |                     |                       | Steering performance                         | ~    |          |     |
| Shock absorbers  |   |                      |                        |                     |                       |  | ~    |          |     |
|  |   |                      |                        |                     |                       | Air Conditioning / Heater                    |      |          |     |
| Operation Operation  |   |                      |                        |                     |                       |  |      |          |     |
| Interior Comments rear right seat stains   |   |                      |                        |                     |                       | Electrical / Accessories                     | 'S   |          |     |
| Seats  | rear rights                                     | seat stains          |                        |                     |                       | Head lights                                  | ~    |          |     |
| Carpets  | Average   |                      |                        |                     |                       | Tail lights                                  | ~    |          |     |
|  |   |                      |                        |                     |                       | Indicators                                   | ~    |          |     |
| Panels   | Average   |                      |                        |                     |                       | Dashboard warning lights                     | ~    |          |     |
| Dashboa  | rd steering w                                   | neel cover worn      |                        |                     | Wipers (front & rear) | ~  |      | <u> </u> |     |
|  |   |                      |                        |                     |                       | Window winder FL                             | ~    |          |     |
| Constal  |   |                      |                        |                     |                       | Window winder FR                             | ~    |          | ļ   |
| <u>General Comments</u>  |   |                      |                        |                     |                       | Window winder RL                             | ~    |          | ļ   |
|  |   |                      |                        |                     |                       | Window winder RR                             | ~    |          | ļ!  |
|  |   |                      |                        |                     |                       | Rear view mirrors                            | ~    |          | ļ   |
|  |   |                      |                        |                     |                       | Radio (basic test only)                      | ~    |          |     |
| CD (basic  |   |                      |                        |                     |                       |  | ~    |          |     |
| Number of keys   |   |                      |                        |                     |                       |  | 2    |          |     |
| Road Conditions During Test Drive:     Dry     Central locking   |   |                      |                        |                     |                       |  | ~    |          |     |
| Engine Timing Mechanism: Timing Chain Remote locking   |   |                      |                        |                     |                       |  |      |          | ~   |
| Suidense of Cam Bolt Donlassmont, Nat Auglischla, Kms.   |   |                      |                        |                     |                       |  |      |          | ~   |
| Evidence   | ог сант вен керіас                              | ement: N             | lot Applicable         | Kms:                |                       | Reversing camera                             |      |          | ~   |
| Inspected by: Kyle Mills-Brown Date: 02 Apr 2019   |   |                      |                        |                     |                       |  |      |          |     |

I have read and understood this condition guide.

Name: .....

Signature: .....