

Basic Vehicle Condition Guide

Reg Expiry:

Report ID: 19,151,676

Version: 1

Created: 08 Apr 2019

Make: Model: Toyota Hiace **Body Style:** Van Year:


Registration:

WoF Expiry: **Odometer: Good No:** 14 Mar 2020 183,407 Kms 19151676 VIN: 7AT0H60FX19000862 **Next Service:** Unknown Service History:

Note: This report is not a warranty

2008

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|--------------------------------|--|--|
| Seats | Good | | |
| Carpets | Small hole in drivers footwell | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

08 Apr 2019 Inspected by: Murray Craig Date:

Name:

| Pass | Fail | N/A |
|-------|---------|---------------------------------------|
| | | L |
| | | |
| ~ | | |
| ~ | | |
| ~ | | |
| • | | |
| | | |
| ~ | | |
| ~ | | |
| • | | |
| | | |
| ~ | | |
| ~ | | |
| | | ~ |
| ~ | | |
| ~ | | |
| | | |
| ~ | | |
| ~ | | |
| depth | of tyre | es) |
| 8 | 3 | mm |
| ġ | 9 | mm |
| ġ | 9 | mm |
| 8 | 3 | mm |
| | Yes | |
| | | |
| ~ | | |
| ~ | | |
| ~ | | |
| | | |
| ~ | | |
| | | |
| ~ | | |
| ~ | | |
| ~ | | |
| ~ | | |
| ~ | | |
| ~ | | |
| ~ | | |
| | | ~ |
| | | ~ |
| ~ | | |
| ~ | | |
| ~ | | |
| 1 | | |
| ~ | | |
| ~ | | |
| | | ~ |
| | | ' |
| | | マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ |

Signature: