

Report ID: 19,152,366 Version: 1 09 Apr 2019 Created:

| Make: | Daihatsu | Model: | Sirion | Body Style: | Hatchback | | Pass | Fail | N/A |
|---|--------------------------|-----------------|------------------------|--------------------|----------------------|------------------------------|---------|---------|-----|
| Year: | 2008 | Registration: | EPU440 | Reg Expiry: | 14 Aug 2019 | Engine | | | |
| WoF Expiry: | 10 Aug 2019 | Odometer: | 148,123 Kms | Good No: | 19152366 | Oil level | ~ | | |
| VIN: | JDAM301S001089454 | Next Service: | 149000 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or | | | | | | Noise | ~ | | |
| diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | P SC W | -0 | S SC P SC | -161- | SC | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust SSC S | | | | | | Operation | ~ | | |
| PT = paint defect | | | | | | Noise | ~ | | |
| C = crack | | | | | SC | Clutch | | | ~ |
| P = pin dent | HID | | | | ᅰ | CV joints | ~ | | |
| * = decals | sc 916 | | | - Jul | ALD S | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | - | | |
| W = significant scuffs SC W SC S SC W SC | | | | | | Performance | ~ | | |
| Deskulas | | Note: son | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| | pection Comments | | | , , | , , | Tyres (lowest observed tread | d depth | of tyre | es) |
| Tow eye cover in rear bumper missing. Stonechips on windscreen. AC not cold. | | | | | | Left front 4 mm | | | |
| | | | | | | Right front | | 5 | mm |
| | | | | | | Left rear | | 4 mm | |
| Conditions During Body Inspection: Day | | | | | | Right rear | | 4 | mm |
| Conditions During Body Inspection: Dry | | | | | | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Surface rust | t on top radiator panel. | Surface rust on | front crossmember. | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | • | | |
| | | | | | | Operation | | | |
| Interior Comments | | | | | | Electrical / Accessories | | • | |
| Seats | Average | | | | | Head lights | ~ | | |
| | | | | | | Tail lights | ~ | | |
| Carpets | Average | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Fallels | - | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Average | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| Drives ok . | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | I | |
| Pood Conditions During Test Driver Day | | | | | | Central locking | 2 V | | |
| Road Conditions During Test Drive: Dry | | | | | | Remote locking | ~ | | |
| Engine Tir | ming Mechanism: | Timing | Chain | | | Sat. Nav. (basic test only) | - | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | | | | • | | | | | |
| Inspected by: Roger King Date: 09 Apr 2019 | | | | | | | | | |
| | | | | | | | | | |

Name: