

Report ID: 19,152,769 Version: 6 17 Dec 2019 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	GCC732	<b>Reg Expiry:</b>	13 Oct 2019	Engine		1	
WoF Expiry:	18 Dec 2020	Odometer:	221,861 Kms	Good No:	19152769	Oil level	~		
VIN:	MNAUMFF50BW1013	Next Service:	228000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	s sc	-01-	D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = ruct SSC						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	~		
P = pin dent						CV joints			~
* = decals SC 919 DP						Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs S P SC SP P SC SC						Performance	~		
						Hand Brake	~		
Body inspection comments						Tyres (lowest observed treat	-	of tyre	 >s)
Stonechips on windscreen. Screw holes in dash. Wear on steering wheel.									mm
		5				Right front		5 4	mm
						Left rear		+3	mm
Canalitian	Dunin n De du la s		NA			Right rear			mm
Conditions During Body Inspection: Wet						Right rear 4 mm   Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Average condition .						Suspension performance	~		
/ Weldge eo						Steering performance			
						Shock absorbers	レ レ		
							V		
						Air Conditioning / Heater			
Interior Comments						Operation			
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
General Comments						Window winder FR	~		
						Window winder RL	~		ļ
Drives ok.						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Timing Mechanicmy Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Increate	Inspected by: Roger King Date: 17 Dec 2019								
Inspected by. Roger King Date: 17 Dec 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....