

Report ID: 19,154,171 Version: 1 09 Apr 2019 Created:

Signature:

Make:	BMW	Model:	Z3	Body Style:	Convertible		Pass	Fail	N/A
Year:	1999	Registration:	FBG450	Reg Expiry:	01 Aug 2019	Engine	I	L	I
WoF Expiry:		Odometer:	162,153 Kms	Good No:	19154171	Oil level	~		
VIN:	WBACH72080LD8261	Next Service:	• -	Service Histor		Smoke & fumes	~	1	
						Performance	~		
	port is not a warranty		c			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S	-0	S		SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc				SW.	Operation	~		
R = rust					THIA	Noise	~		
PT = paint defect C = crack						Clutch	~		
P = pin dent	Ho					CV joints	~		~
* = decals	sc pp				EIPE	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
		Notorcom	L defects ^Q blomich		layed in the diagram				
Body Ins	pection Comments	Note: son	le délects à blemish	les may not be disp	layed in the diagram	Hand Brake	 		
Crack on the windscreen						Tyres (lowest observed tread depth of tyres)			
RL wheel badge missing						Left front	4.5		mm
						Right front		.5	mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	-	inet inspectio	on comments			Suspension			
Excessive engine oil leak Transmission and steering reck oil leak						Suspension performance		~	
Differential oil leak						Steering performance	~		
Underbody surface rust FR and FL shock absorber bump stopper split						Shock absorbers	~		
Thundres	noek absorber barnp se	opper spire				Air Conditioning / Heater			
Interior						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ira j					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
Driver seat insecure (moving forward) Rear view mirrors operation noisy						Window winder RR			~
Front suspension imbalanced						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		1
Road Con	ditions During Tes	t Drive	Dry			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
с						L			1
Inspecte	d by: Sudhin Ramach	andran				Date: 09 Apr 20	19		

I have read and understood this condition guide.

Name: