

Report ID: 19,154,850 Version: 1 09 Apr 2019 Created:

Make:	Lexus	Model:	GS300	Body Style:	Sedan		Pass	Fail	N/A
Year:	2006	Registration:	HYQ927	Reg Expiry:	02 Jul 2019	Engine			
WoF Expiry:	18 Mar 2020	Odometer:	164,631 Kms	Good No:	19154850	Oil level	~		
VIN:	JTHBH96S605046786	Next Service:	166000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC W		S SC S P SC		s	Performance	~		
Key:		-0	33C 3F3C			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc			210	HIVS	Operation	~		
PT = paint defe		r I		$\left(\left \left(\right) \right\rangle \right)$	7011	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	LENCE HIS				2414	CV joints	~		
* = decals	SRSC 91				ELD'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC W S SC SC W S SC						Performance	~		
Podylogr	action Commonts	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Dent in chrome trim on RR door. Rust under paint in LF corner of bonnet.						Tyres (lowest observed tread depth of tyres)			es)
Dent in enrome till for fin door. Nust under paint in Er comer of bonnet.									mm
						Right front		5	mm
						Left rear		7	mm
Condition	s During Body Ins	nection:	Dry			Right rear		3	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good condi	tion.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Seats Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
					J	Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
Brakes squeal occasionally.						Window winder RR	~		
Drives well.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	I	L
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-
L	•								1
Inspected by: Roger King Date: 09 Apr 2019									

I have read and understood this condition guide.

Name:

Signature: