

Report ID: 56,565


Version: 2

Created: 16 Apr 2019

Make:	Mini	Model:	Cooper S	Body Style:	Hatchback
Year:	2009	Registration:	FEN731	Reg Expiry:	10 Jan 2020
WoF Expiry:	22 Apr 2020	Odometer:	164,640 Kms	Good No:	19154897
VIN:	WMWMF72010TT4759	Next Service:	175000	Service History	y: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Road Conditions During Test Drive: Dry

Timing Chain **Engine Timing Mechanism:**

Evidence of Cam Belt Replacement: Not Applicable Kms:

13 Apr 2019 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine	•	•	•
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	\(\times \)		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	.0	mm
Right front	3	.0	mm
Left rear	4	.0	mm
Right rear	4	.0	mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

Signature: