

Report ID: 19,155,519 Version: 1 17 May 2019 Created:

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2010	Registration:	FMB160	Reg Expiry:	16 Nov 2019	Engine	I	<u> </u>		
WoF Expiry:	13 Mar 2020	Odometer:	125,778 Kms	Good No:	19155519	Oil level	~			
VIN:	KL3JA695JAK677346	Next Service:	126500	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		f	Danta harra nat	harry alternatively at an	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0	SC S SC	-M-	s	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent				The		Operation	~			
R = rust PT = paint def				\prod	JHIH	Noise	~			
C = crack				$+ \mathbf{\nabla}$		Clutch			~	
P = pin dent					세비	CV joints	~			
* = decals				The	ELLEN	Wheel bearings	~			
SC = stone chips						Brakes				
W = significan	t scuffs	$- \emptyset$				Performance	~			
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~			
Body Insp	pection Comments				ayea the alagian	Tyres (lowest observed tread	-	oftvre		
						Left front 4.3 mm				
						Right front	4	-	mm	
						Left rear		.2	mm	
Conditions Duving Rody Inspections						Right rear			mm	
Conditions During Body Inspection: Dry						Right rear 4.9 mn Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	ody inspection	-				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	v			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats Good						Head lights	~			
Jeals						Tail lights	~			
Carpets	Good						v v			
Dam-1-	Good					Dashboard warning lights	<i>v</i> <i>v</i>			
Panels						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FE	<i>v</i> <i>v</i>			
General Comments						Window winder RL	v v			
						Window winder RE	<i>v</i> <i>v</i>			
						Rear view mirrors	<i>v</i> <i>v</i>			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2		L	
						Central locking	2			
Road Conditions During Test Drive: Dry						Remote locking	<i>v</i> <i>v</i>			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~	
Evidence of Cam Belt Replacement: Yes Kms: 118,090						Reversing camera			~	
					-,					
Inspecte	Inspected by: Melissa Haggerty Date: 17 May 2019									

I have read and understood this condition guide.

Name:

Signature: