

Report ID: 19,156,249 Version: 1 29 May 2019 Created:

Signature: .....

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	1997		WC1330	Reg Expiry:	04 May 2019	Engine			
WoF Expiry:		Odometer:	367,401 Kms	Good No:	19156249	Oil level	~		
VIN:	7A431LN8508503770	Next Service:	507710114115	Service Histor		Smoke & fumes	~		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					Performance	~		
	port is not a warranty		с I II	<b>D</b>	1 B A I	Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	•		
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		sc o	S D SC			Radiator / Hoses (visual)	~		-
S = scratch	STE	A CO			The	Transmission	•		
D = dent	SDRSCW			1n-		Operation	~		
R = rust				1 M	JHIH	Noise	~		
PT = paint defe C = crack				+	S D R	Clutch	~		
P = pin dent						CV joints	~		-
* = decals	s sc PIP			AL.		Wheel bearings	-		
SC = stone chi	/	20		A		Brakes	~		L
W = significant	t scuffs	sc V	S D SC			Performance	~		T
						Hand Brake	<i>v</i> <i>v</i>		<u> </u>
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftwo	
Stone chips front window screen						Tyres (lowest observed tread depth of tyres)   Left front 6.4 mm			
							6		mm
						Right front	5		mm
						Left rear		8.6 m	
Conditions During Body Inspection: Dry						Right rear	0.0		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	ody inspection	meenspeede	<u>in comments</u>			Suspension			
No underbo	buy inspection					Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
Interior Comments						Operation			~
	tear					Electrical / Accessories	1		
Seats						Head lights	~		<u> </u>
Carpets	rips					Tail lights	~		<u> </u>
	worn					Indicators	~		<u> </u>
Panels	wom					Dashboard warning lights	~		<u> </u>
Dashboa	rd cracks					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concerto						Window winder FR	~		<u> </u>
	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)			~
L						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking			~
						Remote locking			~
-	ming Mechanism:	Cambelt		14	–	Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 33	34,117	Reversing camera			~
	d by Molices Lines					Dete: 30 Mar 20	10		
Inspected	d by: Melissa Haggert	Ly				Date: 29 May 20	לוי		

I have read and understood this condition guide.

Name: .....