

Report ID: 19,156,254

Pass

~

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine Oil level Smoke & fumes

Noise

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Sat. Nav. (basic test only)

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

15 Apr 2019 Created:

Fail

N/A

~

mm

mm

mm

 mm

5

V

/

1

~

1


2

Yes

Make:	Chrysler	Model:	PT Cruiser	Body Style:	SUV
Year:	2008	Registration:	ARTSKL	Reg Expiry:	16 Jul 2019
WoF Expiry:	29 May 2019	Odometer:	66,787 Kms	Good No:	19156254
VIN:	1A8F4B8BX7T536343	Next Service:	74500	Service History	/: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen.

Conditions During Body Inspection: Dry
--

<u>Under Carriage & Under Bonnet Inspection Comments</u>

Interior Comments					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement:

I have read and understood this condition guide.

Kms:	Reversing camera 🗸		
	Date: 15 Apr 2019		
Name:	Signature:	-	