

Basic Vehicle Condition Guide

Report ID: 19,156,470


Version: 3

Created: 12 Nov 2019

Make: Model: Mazda Axela **Body Style:** Hatchback Year: 2009 Registration: KKZ883 Reg Expiry: 10 Mar 2020 WoF Expiry: **Odometer:** 23 Apr 2020 130,213 Kms **Good No:** 19156470 VIN: 7AT0C13JX17106204 Next Service: 140000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	dash pad melted effect		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	\(\times \)				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	✓ ✓				
Transmission					
Operation	~				
Noise	~				
Clutch	~				
CV joints	VVV				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	'				
Tyres (lowest observed tread depth of tyres)					
Left front	2	.0	mm		
Right front	2	.0	mm		
Left rear	2.0		mm		
Right rear	2.0		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	~				
Shock absorbers 🗸					
Air Conditioning / Heater					
Operation 🗸					
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	\(\structure{\chi} \)				
Dashboard warning lights	~				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \				
Window winder RR					
Rear view mirrors	V				
Radio (basic test only)					
CD (basic test only)	~				
Number of keys	1				
Central locking	/		-		
Remote locking	~				
Sat. Nav. (basic test only)			'		
Reversing camera					

I have read and understood this condition guide.

Greg Morgan

Name:

Signature:

12 Nov 2019

Date: