

Report ID: 19,157,328 Version: 3 29 Jun 2019 Created:

Make: Hyundai Model: Sonata Body Style: Sedan		Pass Fa	ail N/A
Year:2009Registration:FBG530Reg Expiry:07 Nov 2019	Engine		
WoF Expiry: 27 Jun 2020 Odometer: 220,831 Kms Good No: 19157328	Oil level	~	
VIN: KMHET41DMAA70636 Next Service: - Service History: Yes	Smoke & fumes	v	
	Performance	v	
Note: This report is not a warranty	Naina	v	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recomme	d or	•	
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	Coolant condition	~	
	Performance	~	_
Key: SD SD SD SD SD P	Radiator / Hoses (visual)	v v	
S = scratch	Transmission	V	
D = dent	Operation	~	
	Noise	v v	
PT = paint defect C = crack	Clutch	~	
P = pin dent			~
*= decals SC QQ	CV joints		
SC = stone chips	Wheel bearings	~	
W = significant scuffs S D D D S S	Brakes		
	Performance		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagr			
	Tyres (lowest observed tread	•	
	Left front	7	mm
	Right front	6	mm
	Left rear	7	mm
Conditions During Body Inspection: Wet	Right rear	6	mm
	Spare	Ye	es
Under Carriage & Under Bonnet Inspection Comments	Suspension		
Front wheel drive	Suspension performance	~	
	Steering performance	~	
	Shock absorbers	~	
	Air Conditioning / Heater		
Interior Comments	Operation	~	
Interior Comments	Electrical / Accessories		
Seats Average	Head lights	~	
Carpets	Tail lights	~	
	Indicators	~	
Panels Poor, boot panels missing	Dashboard warning lights	~	
Average	Wipers (front & rear)	~	
Dashboard	Window winder FL	~	
	Window winder FR	~	
<u>General Comments</u>	Window winder RL	~	
	Window winder RR	~	
	Rear view mirrors	~	
	Radio (basic test only)	~	
	CD (basic test only)	~	
	Number of keys	2	
Road Conditions During Test Drive: Wet	Central locking	~	
	Remote locking	~	
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera		~

I have read and understood this condition guide.

Name: .....

Signature: .....