

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or		~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	Cooling System			
	Coolant condition	~		
Kow SC W SP P D	Performance	~		
Key: Sc W St I St	Radiator / Hoses (visual)	~		
	Transmission			
R = rust	Operation	~		
PT = paint defect	Noise	~		
C = crack	Clutch			~
P = pin dent	CV joints	~		
*= decals SC 919	Wheel bearings	~		
SC = stone chips	Brakes			
W = significant scuffs S SC S P	Performance	~		
Redular protection Comments Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~		
Body inspection comments	Tyres (lowest observed tread	-	of tyre	s)
R/R Taillight Cracked ,	Left front	7.0		mm
	Right front	6.0	-	mm
	Left rear	4.(mm
	Right rear			
Conditions During Body Inspection: Dry		4.(-	mm
Under Carriage & Under Bonnet Inspection Comments	Spare		N/A	
Oil seepage lower engine area,	Suspension			
On seepage lower engine area,	Suspension performance	~		
	Steering performance	~		
	Shock absorbers	~		
	Air Conditioning / Heater			
Interior Comments	Operation	~		
Good	Electrical / Accessories			
Seats	Head lights	~		
Carpets Good	Tail lights	~		
	Indicators	~		
Panels Good	Dashboard warning lights	~		
Dashboard Good	Wipers (front & rear)	~		
Dashboard	Window winder FL	~		
	Window winder FR	~		
<u>General Comments</u>	Window winder RL	~		
Service Due,	Window winder RR	~		
	Rear view mirrors	~		
	Radio (basic test only)	~		
	CD (basic test only)	~		
	Number of keys	2		
Road Conditions During Test Drive: Dry	Central locking		~	
	Remote locking		~	
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:	Reversing camera			~
		·		
Inspected by: Chris Buckley	Date: 16 Apr 20	19		

I have read and understood this condition guide.

Name:

.....

Signature:

Report ID: 19,158,224

Pass

V

V

1

17 Apr 2019

Fail

V

N/A

Version:

Created: