

Report ID: 56,573 Version: 3 26 Apr 2019 Created:

Make:	Peugeot	Model:	407	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2006		MBZ893	Reg Expiry:	26 Oct 2019	Engine			I	
WoF Expiry:	30 Apr 2020	Odometer:	119,641 Kms	Good No:	19158276	Oil level	~			
VIN:	VF36E3FZF21175140	Next Service:	,	Service Histor		Smoke & fumes	~			
					-	Performance	~			
	port is not a warranty		с I II	D		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:		-0	S S			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent						Operation 🖌				
R = rust				1 M	JHIA	Noise	~			
PT = paint def C = crack				+		Clutch	•		~	
P = pin dent	Ho					CV joints	~		•	
* = decals	- MIK			AL-	ENPR-	Wheel bearings	-			
SC = stone chips						<u>_</u>	v			
W = significant scuffs						Brakes				
		Nata				Performance	~			
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~	<u> </u>	<u> </u>	
Trim damage on drivers door					Tyres (lowest observed tread depth of tyres)					
						Left front	3.		mm	
						Right front	3.	0	mm	
						Left rear	8.	8.0 mm		
						Right rear	8.0 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
Steering performance							~			
Shock absorbers							~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Compete	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	Good					Wipers (front & rear)	~			
Dashboa	ra					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
Heater display not working properly						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	~			
			-			Remote locking	~			
Engine Timing Mechanism: Cambelt Sat. Nav. (basi									~	
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 88	3,810	Reversing camera			~	
L										
Inspected by: J Offesen Date: 17 Apr 2019										

I have read and understood this condition guide.

Name:

Signature: