

Basic Vehicle Condition Guide

Report ID: 19,158,461


Version: 2

Created: 26 Jun 2019

Make: Model: Hyundai lx35 **Body Style:** SUV Year: 2010 Registration: FLY118 Reg Expiry: 12 Jul 2019 WoF Expiry: **Odometer: Good No:** 13 Aug 2019 307,509 Kms 19158461 VIN: KMHJU81VSAU11723 Next Service: 272874 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



200/mspection comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak,

| <u>Interior Comments</u> | | | |
|--------------------------|--------------------------------------|--|--|
| Seats | drivers seat ripped, wear and tear , | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara Date: 26 Jun 2019

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | • | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | · · | | mm |
| Right front | 5 | | mm |
| Left rear | 5 | | mm |
| Right rear | 5 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | <i>V</i> | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | • | | |
| Operation | | ·/ | Ι |
| Electrical / Accessories | | | |
| Head lights | | | Т |
| Tail lights | V | | |
| Indicators | | | |
| | ' | | |
| Dashboard warning lights | V | | |
| Wipers (front & rear) | v | | |
| Window winder FL | ' | | |
| Window winder FR | / | | |
| Window winder RL | / | | |
| Window winder RR | • | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | ı | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | 1 |

I have read and understood this condition guide.

Name:

Signature: