

Basic Vehicle Condition Guide

Report ID: 19,159,361


Version: 1

Created: 27 Apr 2019

Make: Model: Subaru Outback **Body Style:** SUV Year: 2010 Registration: FJH994 Reg Expiry: 26 Oct 2019 WoF Expiry: **Odometer: Good No:** 02 May 2020 198,546 Kms 19159361 VIN: **Next Service:** JF2BR9K95AG010101 205000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Windscreen chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Greg Morgan

Evidence of Cam Belt Replacement: Yes

Kms: 103,032

| Create | u. 2 | / Apr 2 | 019 |
|---------------------------------------|---------------------------------------|---------|----------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | \(\times \) | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | V | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | • | • |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 6 | .0 | mm |
| Right front | 6 | .0 | mm |
| Left rear | 6 | .0 | mm |
| Right rear | 6.0 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | V V V V V V | | |
| Window winder FR | <u></u> | | |
| Window winder RL | , , , , , , , , , , , , , , , , , , , | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | <i>v</i> | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | | |
| Central locking | <i>V</i> | | |
| Remote locking | - V | | |
| Sat. Nav. (basic test only) | | | ./ |
| · · · · · · · · · · · · · · · · · · · | | | ., |
| Reversing camera | | | <u> </u> |

I have read and understood this condition guide.

| Name: | | | |
|-------|--|--|--|
| | | | |

11 Apr 2019

Date: