

Report ID: 19,160,591 Version: 1 13 Apr 2019 Created:

Make:	Foton	Model:	Tunland	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JJP279	Reg Expiry:	09 May 2019	Engine			
WoF Expiry:	02 Nov 2019	Odometer:	67,852 Kms	Good No:	19160591	Oil level	~		
VIN:	LVAV2MBB7FJ051205	Next Service:	78,269	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	avation is made	for one and miles as	Danta hava nat	hoon dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SSC	-0	SC S D SC	-161-	S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	D SC			The	S SC	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack						Clutch	~		
P = pin dent					세비	CV joints		~	
* = decals	sc 916				S SC	Wheel bearings	~	•	
SC = stone chips						Brakes			
W = significant scuffs S D SC SC SC SC SC S D C W						Performance	~		
		Note: son	he defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•		 >s)
Tailgate latch broken Deck cover hocks broken									 mm
Deckeover						Right front			mm
						Left rear		.5	mm
						Right rear			-
Conditions During Body Inspection: Dry						Spare	3.3 mm		mm
Under Carriage & Under Bonnet Inspection Comments					· ·	Yes			
Front diff oil leak						Suspension Suspension performance			
Right front outer c/v boot split							~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	bood liner	stains door pane				Indicators	~		
Panels			9004			Dashboard warning lights	~		
Dashboa	d glove box latch console arm rest broken					Wipers (front & rear)	~		
						Window winder FL	~		
Ganaral	<u>Comments</u>					Window winder FR	~		
						Window winder RL	~		
						Window winder RR		~	
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1	1	
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ming Machanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi cam Belt Replac	ernent: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: lan Dunn Date: 13 Apr 2019									

I have read and understood this condition guide.

Name:

Signature: