

Basic Vehicle Condition Guide

Report ID: 19,160,639


Version: 4

Created: 23 Jul 2019

Make: Model: Toyota Prius **Body Style:** Hatchback Year: 2010 Registration: LJE736 Reg Expiry: 27 Jan 2020 WoF Expiry: **Odometer:** 30 Apr 2020 110,733 Kms **Good No:** 19160639 VIN: 7AT0H637X18232626 Next Service: 120,000kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: lan Dunn Date: 15 Apr 2019

Pass	Fail	N/A
~		
~		
~		
~		
	•	
~		
~		
~		
	•	
~		
~		
		~
~		
~		
~		
~		
d depth	of tyre	es)
6.2		mm
6	.2	mm
3.1		mm
2.9		mm
	Yes	
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
~		
1		
1		
1		
1		·
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

I have read and understood this condition guide.

Name:

Signature: